
Assembly Instructions-C26b BNC

ORIGINAL CRIMP PLUGS




ferrule


boot

ferrule clamp plug body assembly nut assembly

Amphenol Number	Connector Type	Cable RG-/U	Hex Crimp Data			Stripping Dimensions, inches (mm)		
			Cavity for Contact	Cavity for Outer Ferrule	Die Set for Tool 227-944*	а	b	с
31-351	BNC Plug	58, 141	—	.213(5.4)	227-1221-11	.922(23.4)	.516(13.1)	.250(6.3)
31-359	BNC Plug	59, 62, 140	—	.255(6.5)	227-1221-13	.922(23.4)	.516(13.1)	.250(6.3)
31-371	BNC Plug	174, 179, 187, 188, 316	—	.128(3.2)	227-1221-3	.797(20.2)	.516(13.1)	.250(6.3)



Step 3









cable dielectric must

butt insulator as shown



Step 5

Step 6



lip of boot must be firmly posi-Step 7 tioned in body groove

- Step 1 Install boot and slide outer ferrule onto cable as shown prior to stripping cable.
- Step 2 Strip cable jacket, braid and dielectric to dimensions shown. See attached table for dimensions. All cuts are to be sharp and square. Important: DO NOT nick braid, dielectric, and center conductor when cutting. Tin center conductor using soft solder per QQ-S-571 comp Sn 60. Avoid excessive heat while tinning to prevent swelling of cable dielectric.
- **Step 3** Slightly flare out end of cable braid as so as to facilitate insertion onto ferrule clamp nut assembly. Important: DO NOT comb out braid.
- Step 4 Install ferrule clamp nut assembly onto cable so that ferrule portion slides under braid and insulator butts flush against cable dielectric. Slide outer ferrule over braid and up against nut. Make sure no slack exists in braid. Crimp outer ferrule with tool specified in table above, keeping cable dielectric bottomed against insulator.
- Step 5 Soft solder center conductor to contact using rosin core per QQ-S-571 comp Sn 60. DO NOT get any solder on outside surfaces of contact.
- Step 6 Screw connector body onto prepared cable termination . Wrench tighten by holding the cable nut assembly STATIONĂRY while ROTĂTING the connector body.
- Step 7 Push body forward and into position as shown to complete assembly.

* for pneumatic crimp tool 227-60, use die sets indicated in this column

X-ON Electronics

Largest Supplier of Electrical and Electronic Components

Click to view similar products for RF Connectors / Coaxial Connectors category:

Click to view products by Amphenol manufacturer:

Other Similar products are found below :

R125315120 8915-1511-000 89674-0827 5916-1103-603 0106-001-000 6-0001-3 6001-7071-019 6002-7051-003 6002-7551-202 6059674-1 619550-1 630059-000 M39012/25-0021 M39012/79-3008 M39030/3-01N M39030/3-03N M3933/25-36N 6500-7071-046 6501-1071-002 M83723/72W2457N 6769 CX050L2AQ 7002-1541-010 7002-1572-002 7003-1572-002 7004-1512-000 7009-1511-004 7010-1511-000 7029-1511-060 7101-1541-010 7101-1571-002 7105-1521-002 7145-1521-002 7209-1511-011 7210-1511-012 7210-1511-015 7210-1511-019 7210-1511-040 7225-1512-050 7242-1511-000 73137-5015 73251-0111 73251-0672 73276-1501 73366-0013 73404-2300 73413-6080 73415-5721 7405-1521-005 7405-1521-802