



Derek Imschweiler, Product Manager
dimschweiler@stwconn.com

Bel Stewart Connector
11118 Susquehanna Trail South
Glen Rock, PA 17327
Phone: (717) 235-7512
Fax: (717) 235-7954

Product Change Notification: PC600014
Bel Stewart Connector Customers and Sales Force,

1/30/13

At Bel Stewart, we are constantly reviewing our connector designs and upgrading them so that we can provide the best possible product to the market. We have recently evaluated our horizontal and angled series of SS-60300 CAT6a jacks and have identified a change we plan to make to the product:

Plating change to remove gold flash plating from non-essential areas of the contact array.

- This change is in response to the ever increasing cost of gold and our efforts to minimize any product cost increases associated with rising commodity prices.
- The new plating specification will eliminate gold flash plating in areas outside of the plug / jack contact zone and solder tail zones.

Since this will not affect plating at the plug / jack interface or the solder tails, we do not anticipate any mechanical or electrical changes to the connector as a result of these changes. We plan to implement the design changes after May 1st 2013. The date modified product starts shipping will depend upon customer demand and stock levels at that time. If you have any issues with these changes, contact your local Bel Stewart Sales representative, otherwise we will consider this change acceptable and move forward with the implementation.

Thank you,

Derek Imschweiler
Product Manager

X-ON Electronics

Largest Supplier of Electrical and Electronic Components

Click to view similar products for [Modular Connectors / Ethernet Connectors](#) category:

Click to view products by [Stewart Connector / Bel](#) manufacturer:

Other Similar products are found below :

[RJE231881317T](#) [MP1010RX-1000](#) [MP44RX-1000](#) [GAX-3-66](#) [GAX-8-62](#) [93606-0253](#) [GD-A-44](#) [GDCX-PA-66-50](#) [GDCX-PN-64](#) [GDCX-PN-66](#) [GDCX-PN-66-50](#) [GDLX-A-66](#) [GDLX-A-88](#) [GDLX-N-66](#) [GDLX-S-88K](#) [GDTX-S-88-50](#) [GDX-PA-1010](#) [GLX-N-1010M-BLK](#) [GLX-N-44M](#) [GLX-S-88M-BLK](#) [GMX-N-1010](#) [GMX-S-1010](#) [GMX-S-66](#) [GMX-SMT2-N-1010](#) [GMX-SMT2-N-64-50](#) [GMX-SMT2-S6-88](#) [GMX-SMT4-N-88](#) [GPX-2-64](#) [GRT1-BT1-5](#) [GSGX-N-2-88](#) [GSX-NS2-88-3.05](#) [GSX-NS2-88-3.05-50](#) [GSX-NS-88-3.05-30](#) [GSX-NS-88-3.05-50](#) [GSX-NS-88-3.68](#) [1-1775629-2](#) [GWLX-S-88-GR](#) [GWLX-S9-88-YG](#) [1300500326](#) [1300500227](#) [1300530003](#) [1300570002](#) [1324640-4](#) [RJ11FTVC2G](#) [RJ11FTVC2N](#) [RJFTVX2SA1G](#) [132764-001](#) [1400000](#) [1413176](#) [1413235](#)