Product Information

KHP 81

Part no. T0051516899

Description

Safety rest with Stop + go function. Operated by a fibre optic sensor for use with WSP80 soldering iron and WFE extraction unit.

The unit comprises :-

WDH 10 safety rest part no. T0051516172

KHP pneumatic control unit part no. T0058735818.

KHE 81

Part no. T0051516799

Description

Safety rest with Stop + go function, operated by a fibre optic sensor for use with WSP80 soldering iron and WFEP extraction unit.

The unit comprises :-

WDH 10 safety rest part no. T0051516172

KHE electric control unit part no. T0058735819.

Operation

The safety rests with stop + go functions are recommended accessories for use with WP80FE soldering irons used with the WFE or WFEP bench top fume extraction units. A fibre optic sensor switches the extraction unit on, when the soldering iron is removed from the rest and after a short delay the extraction unit is switched off when the soldering iron is replaced in the rest.

Advantage

This will reduce energy cost and increase the time between servicing by lengthening the life of the filters in the extraction units.

Associated product.

For use with KHE81 /KHP81, a second safety rest with fibre optic sensor to extend the use of the fume extraction unit to operate with two WSP80 FE soldering irons.

Part no T0051516172.

X-ON Electronics

Largest Supplier of Electrical and Electronic Components

Click to view similar products for Weller manufacturer:

Other Similar products are found below:

XPE700 ST-4 ST-3 0054005799 0058744845 0054465399 6120 7324 PL138 PTH6 HE35 DXV80 NTD T0051387699 T0051607599

T0052916199 T0053418699 T0053427699 T0053434699 T0053638699 T0054486299 T0058732869 PSI5 HEW60P LT4X CT6E7

51314700 WHP80 WTA1 WTA4 DS227 DX120 RT6MS RTW3MS SP40NUS T0051302699 T0051390699 T0051628899 T0052704299

T0053429699 T0053438699 T0053439699 T0053657199 T0054480299 T0058744730 TC208 CT5AA8 WPT15 WLSK200

WEL.51361699