

# 0CA08-3004



Interface cable set for EA 110 plus i for one or two i-CON (0IC1000A, 0IC1000AC, 0IC1000AXT) or i-CON 2 (0IC2000A, 0IC2000AC, 0IC2000AIT, 0IC2000AXT) soldering stations to connect with the EA110 plus i solder fume extraction (0CA08-002). For protection of the drive motor, the ERSA EA 110 plus i has an automatic cut off feature.

## X-ON Electronics

Largest Supplier of Electrical and Electronic Components

*Click to view similar products for [Ersa manufacturer](#):*

Other Similar products are found below :

[162 BD/SB](#) [0085JD](#) [E008100](#) [ERSA-832VDLF](#) [I-CON2 V](#) [0IC2200VIT](#) [0910BD](#) [0DIG20A84](#) [0450MDJ](#) [ERSA-842SD](#) [ERSA-832ED](#)  
[ERSA-81100J](#) [ERSA-032BD](#) [0612EDLF/SB](#) [0722EN1020](#) [0842UDLF/SB](#) [0832KDLF/SB](#) [0842EDLF/SB](#) [212 MS](#) [0WICKNC1.5/10](#)  
[0212FDLF/SB](#) [42100J](#) [3CA06-1001](#) [0A05](#) [0840CDJ](#) [E033100](#) [E096100](#) [0200MD](#) [0550MD](#) [05X100](#) [0ICV2000AC](#) [E092100](#) [0330KD](#)  
[0670CDJ](#) [0760CD](#) [0890CDJ](#) [0930CD](#) [0A04](#) [0A39](#) [0IC2000A](#) [0IC2000AXT](#) [0SR100](#) [0IC1300](#) [0212BDLF/SB](#) [0212CDLF/SB](#) [0212WD](#)  
[0422ED](#) [0612KDLF/SB](#) [ERSA-MINOR](#) [ERSA-012BD](#) [ERSA-842UD](#)