

Protection cover for MSM 19 and MSM 22



MSM switch is not part of the product

Description

- Protection cover IP 68
- Antibacterial material according to ISO22196
- Protects from dirt
- Replaceable

Characteristics

- Ensures a hygienically surface to avoid the growth of diverse bacteria cultures
- Mechanical Lifetime: More than 200'000 actuations
- Tight according to IP68

References

Mating cover to

Weblinks

[html-datasheet](#), [General Product Information](#), [CE declaration of conformity](#), [RoHS](#), [CHINA-RoHS](#), [CAD-Drawings](#), [Product News](#), [Detailed request for product](#)

All Variants

Diameter	Order Number
19	0098.9277
22	0098.9278

Availability for all products can be searched real-time:<http://www.schurter.com/en/Stock-Check/Stock-Check-SCHURTER>

Packaging unit 10 in a box

X-ON Electronics

Largest Supplier of Electrical and Electronic Components

Click to view similar products for [Schurter](#) manufacturer:

Other Similar products are found below :

[4302.0101](#) [0034.3429](#) [0034.7115](#) [0040.1101](#) [0001.1007.PT](#) [0034.2515](#) [0034.3406](#) [7030.3280](#) [FMAC-0932-1610](#) [FMAC-0934-3610](#) [FMAD-0931-0810](#) [FMBD-B92B-2512](#) [FMBD-B92C-6412](#) [FMW-65-0005](#) [1241.2506](#) [1301.9211](#) [9632.5100](#) [FMAC-091C-1610](#) [FMAD-0932-2510](#) [FMBC-0994-1000](#) [3-101-015](#) [TA35-C324L080C0](#) [4304.5043](#) [4420.0361](#) [4740.3000](#) [5500.2065](#) [5500.2069](#) [5500.2655.01](#) [4303.1061](#) [4400.0341](#) [4430.2907](#) [DKIH-3358-50C8](#) [DKIP-0333-5001](#) [0865.9851](#) [091132B](#) [5120.1006.0.21](#) [CD24.4101.151](#) [3404.0043.11](#) [6136.0137.0210](#) [FMAC-0934-5010](#) [FMBC-A91U-0710](#) [EC12.1101.001](#) [FMAC-0932-2510](#) [FMAC-3RYB-2010](#) [7010714013](#) [1068.1012.1110001](#) [8020.5071](#) [TA35-CFTBLJ04C0](#) [1241.2903.002](#) [1241.2855](#)