



# 

# No hassle warranty

NO HASSL

No waiting.

No shipping charges.

Our commitment to high-quality products and customer service is demonstrated by our industry exclusive "No Hassle" warranty. In the unlikely event that an Amprobe Test Tool requires warranty service, any of our local dealers are authorized to replace it, on the spot.

(note: \$500 MSLP limit)

# ACD-22SW Swivel Clamp Meter

New patented rotating head clamp design allows easy viewing of the measurements in tight or inconvenient to reach places. Simply rotate the body of meter to get an unobstructed view of the LCD display. Rich set of features and CAT III 600V safety reading for use in electrical and HVAC applications.

- TRMS Measurement
- 180 degree rotating head for the perfect display viewing
- Advanced VoltTect non-contact voltage detection
- Slim jaw design with one hand operation
- Measures AC Current up to 400 ACA, AC/DC Voltage up to 600V, Resistance and Capacitance
- Audible continuity
- Auto and manual ranging respectively for quick checks and precise measurements
- Backlight
- Auto power off
- Data hold
- Accommodates conductors up to 1.18" (30mm) in diameter
- Safety CAT III 600 V
- Test leads, battery (installed), Users Manual, Carrying Case and type-K thermocouple are included with the product





# **ACD-22SW Swivel Clamp Meter**

# Data Sheet

## **General Specifications**

Display	3¾ digit liquid crystal display (LCD) with a maximum reading of 3999.
Polarity	Automatic, positive implied, negative polarity indication.
Overrange	(OL) or (-OL) is displayed.
Zero	Automatic.
Low battery indication	The " $\square$ " is displayed when the battery voltage drops below the operating level.
Auto power off	Approx. 10 minutes.
Measurement rate	2 times per second, nominal.
Operating Environment	0°C to 50°C / 32°F to 122°F at <70% relativehumidity.
Storage Ttemperature	-20°C to 60° / -4°F to 140°F, 0 to 80% R.H. withbattery removed from meter.
Accuracy	Stated accuracy at 74°F ±8°F, <75% relative humidity.
Temperature Coefficient	0.1 × (specified accuracy) per °F, (32°F to 66°F, 82°F to 122°F).
Altitude	6561.7 Feet (2000m).
Jaw opening capability	30mm conductor.
Power	1.5 volt battery x2, R03/SIZE AAA.
Battery life	50 hours typical with carbon-zinc. 100 hours typical with alkaline.
Dimensions	240 × 70 × 41mm (9.5 × 2.8 × 1.6 in).
Weight	Approx. 220g (7.7oz.) including battery.
Safety	Designed to meet IEC 61010-1 (EN61010-1) and IEC 61010-2-032 (EN61010-2-032), CATIII 600V class II and pollution degree 2 indoor use comply with CE , CSA

# **Electrical Specifications**

OC Volts	
Ranges	400mV, 4V, 40V, 400V, 600V
Resolution	0.1mV
Accuracy	±(0.5% rdg + 2 dgts)
Input Impedance	400mV:>100MΩ; 4V:10MΩ;40V~600V:9.1MΩ
Overload Protection	600VDC or AC rms To measure millivolts, use "RANGE " button to manually select 400mV range.

### AC Volts (50Hz - 500Hz)

Ranges	4V, 40V, 400V, 600V
Resolution	1mV
Accuracy	±(1.2% rdg + 8 dgts)
	±(1.5% rdg + 8 dgts) on 600V range
Crest Factor	≤3
AC coupled true rms speci	fied from 5% to 100% range
Input Impedance	4V:10ΜΩ;40V~600V:9.1ΜΩ
Overload Protection	600 VDC or AC rms

### AC Current (50Hz - 60Hz)

Ranges	40A , 400A	
Resolution	0.01A	
Accuracy	±(2.0% rdg + 10 dgts) 50 ~ 60Hz	
Crest Factor	≤3	
AC coupled true rms specified from 5% to 100% range		
Overload Protection	400A AC	



# **ACD-22SW Swivel Clamp Meter**

# Data Sheet

### Resistance

Resistance	
Ranges	400Ω, 4kΩ, 40kΩ, 400kΩ, 4MΩ, 40MΩ
Resolution	0.1Ω
Accuracy	±(1.0% rdg + 5 dgts) on 400 $\Omega$ to 400k $\Omega$ ranges
	±(1.5% rdg + 5 dgts) on 4M $\Omega$ range
	±(3.0% rdg + 5 dgts) on 40M $\Omega$ range
Open Circuit Volts	-0.45V dc typical, (-1.2Vdc on 400 $\Omega$ range)
Overload Protection	600VDC or AC rms
Diode Test	
Test Current	0.8mA (approxImate)
Accuracy	±(3.0% rdg + 3 dgts)
Open Circuit Volts	3.0 Vdc typica
Overload Protection	600VDC or AC rms
Continuity	
Range	400Ω
Resolution	1Ω
Audible Indication:	Less than 25 $\Omega$
Response Time	500ms
Overload Protection	600VDC or AC rms
Non-Contact Voltage Indicator	Sense voltage 70V to 600VAC (50Hz ~ 60Hz) beeper chirps and big bright red LED comes on, works when meter dial is on any ranges.
AUXILIARY FEATURES	
Hold	Freeze the latest reading on the display.
Range	Excute manual range mode.
Disable Auto Power Off	Set the DMM to off position, press (RANGE) button, and hold the (RANGE) button while turning the rotary knob to the desired range position. Release the button when LCD displays normally. Note "APO" annunciator is missing from the LCD. The Auto Power Off mode is activated with an "APO" symbol indicating on LCD.



### **ACD-22SW Swivel Clamp Meter**

Data Sheet

Included Accessories One pair test leads 1.5V battery x2 (installed) Carrying case TPK01 thermocouple Users Manual

### Amprobe® Test Tools

website: www.Amprobe.com email: info@amprobe.com Everett, WA 98203 Tel: 877-AMPROBE

### **Amprobe® Test Tools Europe**

In den Engematten 14 79286 Glottertal, Germany Tel.: +49 (0) 7684 8009 - 0

©2010 Amprobe Test Tools. All rights reserved. 08/2010 ACD-22SW\_DS Rev A

# **X-ON Electronics**

Largest Supplier of Electrical and Electronic Components

Click to view similar products for Amprobe manufacturer:

Other Similar products are found below :

 ACD-14-PRO
 3311961
 3474954
 TL35B
 AMP-320
 LCR55A
 TACH-10
 DL248D
 LM-100
 AT-3500
 MLS55-3
 MO-100
 3435058
 3026976

 3435099
 AM-4B
 A-47L
 VL-11R
 4560562
 4544583
 CC-7000
 4313925
 2727795
 3052353
 3086905
 2730690
 2733041
 3503207
 3729989

 KLK15
 TR300
 VC221B
 3AG-312
 30XR-A
 AM-530
 34XR-A
 LM-120
 8008
 ACD-15-TRMS-PRO
 MT5-LEADS
 VT-100
 ACDC-54NAV

 HS-1
 4594135
 ULD-400-T
 2730785
 1990707
 2727851
 3475094
 5XP-A