# T-GAGE® M18T Series Sensor



# Datasheet

18 mm Sensor with Discrete Output and TEACH Configuration

To view or download the latest technical information about this product, including specifications, dimensions, accessories, and wiring, go to <a href="https://www.bannerengineering.com">www.bannerengineering.com</a>.



- Fast 25 ms response time with up to 20 Hz switching speed
- Easy-to-use TEACH configuration without potentiometer adjustments
- · Small, self-contained package; no auxiliary controller needed
- Rugged encapsulated design for harsh environments
- Choice of 2 meter or 9 meter unterminated cable, or 5-pin M12 quick disconnect
- · Product motion not required for sensing
- · Remote configuration available in both Static and Dynamic modes



#### WARNING:

- · Do not use this device for personnel protection
- · Using this device for personnel protection could result in serious injury or death.
- This device does not include the self-checking redundant circuitry necessary to allow its use in
  personnel safety applications. A device failure or malfunction can cause either an energized (on) or deenergized (off) output condition.



#### **WARNING:**

- · N'utilisez pas ce dispositif pour la protection du personnel.
- L'utilisation de ce dispositif pour la protection du personnel pourrait entraîner des blessures graves ou mortelles
- Ce dispositif n'est pas équipé du circuit redondant d'autodiagnostic nécessaire pour être utilisé dans des applications de protection du personnel. Une panne ou un dysfonctionnement du dispositif peut entraîner l'activation ou la désactivation de la sortie.

## Models

Model	Connection 1	D:S Ratio	Sensing Face	Supply Voltage	Output
M18TB8	2 m (6.5 ft) unterminated 5-wire shielded cable	8:1	Integrated lens		Bipolar (NPN and PNP)
M18TB8Q	Integral 5-pin M12 male quick disconnect	0.1	integrated tens	10 V DC to 30 V DC	
M18TB6E	2 m (6.5 ft) unterminated 5-wire shielded cable	6:1	Enclosed plastic face (for food		
M18TB6EQ	Integral 5-pin M12 male quick disconnect	0.1	industry use)		
M18TB14	2 m (6.5 ft) unterminated 5-wire shielded cable	14.1	Cormonium long		
M18TB14Q	Integral 5-pin M12 male quick disconnect	14:1	Germanium lens		

# Overview

The T-GAGE analog sensor is a passive, non-contacting, temperature-based device. It is used to detect objects that are either hotter or colder than the ambient condition and then activate an output.

Although it looks and operates just like an Expert<sup>™</sup> photoelectric sensor, the T-GAGE detects the infrared light energy emitted by objects instead of its own emitted light. The sensor uses a thermopile detector, made up of multiple infrared-sensitive elements (thermocouples) to detect this infrared energy within its field of view (see Sensing Field of View on p. 2).

Original Document 120632 Rev. E

To order the 9 m (30 ft) PVC cable model, add the suffix "W/30" to the cabled model number. For example, M18TB8 W/30. Models with a quick disconnect require a mating cordset.

#### Potential applications include:


- Hot part detection (baked goods, metals, bottles)
- Ejection verification of injection-molded parts
- Flame process verification
- Hot glue detection (packaging equipment, book binding)
- Cold part detection (frozen foods, ice, dairy)
- Roller monitoring



Figure 1. Sensor Features

1. Power LED

- 2. Alarm Output LED
- 3. Push **Button**



Note: The T-GAGE M18T sensor is not intended for absolute temperature measurement or for safety-related fire detection use.



Note: Le T-GAGE M18T n'est pas conçu pour une mesure de température absolue ni pour une utilisation dans le cadre de sécurité pour la détection de feu.

## Indicators


Power ON/OFF LED	Indicates
OFF	Power is OFF
ON Green	Sensor is in Run mode
ON Red	TEACH is active

Output LED	Indicates
OFF	Run Mode: Output is OFF
	2-Point TEACH active: Waiting for Output OFF condition
ON Amber	Run Mode: Output is energized
	2-Point TEACH active: Waiting for Output ON condition
Flashing Amber	Dynamic TEACH active

# Sensing Field of View

Sensing range is determined by the sensor's field of view or viewing angle, combined with the size of the object(s) being detected. The sensor's distance-to-spot size ratio (D:S ratio) is inversely related to the viewing angle; a sensor with a small viewing angle will have a large D:S ratio. The T-GAGE M18T sensors have D:S ratios of 6:1, 8:1 or 14:1. For a sensor with an 8:1 D:S ratio, the sensor spot size is a 1" diameter circle at a distance of 8"; farther from the sensor face the spot size will be larger.

Figure 2. Detection spot size versus distance from sensor



Sensor D:S	Distance from Sensor Face Versus Spot Size										
Ratio	100	200	300	400	500	600	700	800	900	1000	Distance (mm)
6:1	17	33	50	67	83	100	117	133	150	167	
8:1	13	25	38	50	63	75	88	100	113	125	Spot Size (mm)
14:1	7	14	21	29	36	43	50	57	64	71	

# Apparent Temperature

Two factors that have a large influence on apparent temperature are the object's emissivity and whether or not the object fills the sensor field of view.

#### **Object Emissivity**

A "blackbody" is a "perfect" emitter, with an emissivity of 1.0 at all temperatures and wavelengths. Most surfaces emit only a fraction of the amount of thermal energy that a blackbody would. Typical T-GAGE applications will be sensing objects with emissivities ranging from 0.5 to 0.95. Many references are available with tables of emissivity coefficients for common materials. In general, shiny unpainted metals have low emissivity, while non-glossy surfaces have high emissivity.

#### **Shiny Surfaces**

A mirror or shiny surface can redirect an object's emitted energy to an undesired location, or even bring additional unintended thermal energy into the sensor's field of view. See Application Note on p. 7.

## **Object Size**

If the object being detected does not fill the sensor field of view, then the sensor averages the temperature of that object and whatever else is in the sensing field of view. For the sensor to collect the maximum amount of energy, the object should completely fill the sensor field of view. In some applications, when the object is too small, this may not be possible. In such cases, if the object is hot enough, the thermal contrast may still be adequate to trigger the sensor output.

## Installation

# Installation Note

Align the sensor toward the object to be detected. Visually align if possible, or use the alignment device accessory listed in Additional Accessories on p. 8.

# Wiring Diagram



# Sensor Configuration

Configure the sensor using one of two TEACH methods:

- · Two-Point Static TEACH
- Dynamic TEACH

Use the push button or remote input to configure the sensor.

multiple pulses, are d

**Note:** The duration of each remote line pulse (corresponding to a push button "click"), and the period between multiple pulses, are defined as "T": 0.04 seconds < T < 0.8 seconds.

# Push Button Enable/Disable

The push button can be disabled using the remote input wire (gray) to prevent unauthorized adjustment. To disable the push button, connect a normally open switch between the remote input wire and dc common or connect the remote input wire to a digital output on a Programable Logic Controller (PLC). Perform the procedure below to enable or disable the push button, where 0.04 s < T < 0.8 s.

Method	Action	Result
Remote Input	Pulse the remote line four times.	 The push button is enabled or disabled, depending on the previous condition.

# 2-Point Static TEACH

Use 2-Point Static TEACH configuration method for applications where both ON and OFF target conditions can be presented to the sensor statically by the operator. The sensor establishes a single sensing threshold (the switchpoint) midway between the two configured conditions, with the Output ON condition on one side and the Output OFF condition on the other.




**Note:** The sensor returns to RUN mode if the first 2-Point Static TEACH condition is not configured within 60 seconds.



**Note:** After the first condition is configured, the sensor remains in 2-Point Static TEACH configuration until the second condition is configured.

Figure 3. 2-Point Static TEACH



1. Access 2-Point Static TEACH configuration.

Method	Action	Result
Push Button	Press and hold the button for 2 seconds.	Power LED turns Red
Remote Input (0.04 s < T < 0.8 s)	No action required.	Output LED turns Amber

2. Present the output ON condition.

Method	Action	Result
Push Button	Press the button one time.	Output LED turns OFF
Remote Input	Pulse the remote line one time.	Sapat LLS tumb of f

3. Present the output OFF condition.

Method	Action	Result
Push Button	Press the button one time.	<ul> <li>TEACH Accepted</li> <li>Power LED turns Green</li> <li>The sensor configures</li> </ul>
Remote Input	Pulse the remote line one time.	switching threshold and returns to Run mode  2-Point Static TEACH Not Accepted The sensor returns to the beginning of the TEACH configuration.



**Note:** To exit 2-Point Static TEACH configuration without saving a configuration, press and hold the push button for 2 seconds or hold the remote line for 2 seconds. The sensor will return to Run mode without saving a configuration.

# Dynamic TEACH

Use Dynamic TEACH configuration method for applications where both the ON and OFF target conditions can not be presented to the sensor dynamically by the operator. After the configuration has been completed, the threshold at the midpoint is optimized by the sensor halfway between the average signals presented during the Dynamic TEACH configuration.

# 1. Access Dynamic TEACH configuration.

Method	Action	Result
Push Button	Press and hold the button for 2 seconds.	Power LED turns Red
Remote Input (0.04 s < T < 0.8 s)	No action required.	Output LED turns Amber

# 2. Present the sensing conditions.

M	ethod	Action	F	Result
Pι	ısh Button	Press the button two times.		Sensor begins Dynamic TEACH configuration
Re	emote Input	Pulse the remote line two times.	_	Output LED flashes Amber at 2 Hz

# 3. End Dynamic TEACH configuration.

Method	Action	Result
Push Button	Press the button one time.	The sensor ends data collection; configures the threshold
Remote Input	Pulse the remote line one time.	Power LED turns Green     The sensor returns to Run mode

# Hot Operate/Cold Operate Select

Configure the sensor for Hot Operate, or Cold Operate using the remote input wire (gray). Pulse the remote line three times to toggle between Hot and Cold Operate, where 0.04~s < T < 0.8~s.

Method	Action	Result
Remote Input	Pulse the remote line three times.	Hot Operate or Cold Operate is selected, depending on the previous condition.

# Specifications

#### **Temperature Measurement Range**

0 °C to +300 °C (+32 °F to +572 °F) Custom ranges available upon request

#### Sensing Range

Depends on object size and sensing field of view (see Sensing Field of View on p. 2)

#### Wavelength

8  $\mu m$  to 14  $\mu m$ 

#### Distance to Spot Size (D:S) Ratio

6:1, 8:1, or 14:1, depending on model

## Supply Voltage

10 V DC to 30 V DC (10% maximum ripple) 35 mA maximum (exclusive of load)

#### **Output Configuration**

One NPN and one PNP in each model

#### Output Protection

Protected against short-circuit conditions

#### **Output Ratings**

100 mA maximum (each output)
OFF-state leakage current: NPN < 200 microamps; PNP < 10 microamps
NPN saturation: < 200 mV at 10 mA and < 1 V at 100 mA

PNP saturation: < 1.2 V at 10 mA and < 1.6 V at 100 mA

## **Delay at Power-Up**

1.5 seconds

#### **Output Response Time**

25 ms

#### Repeatability (Relative)

#### **Minimum Taught Differential**

3°C

#### Hysteresis

5% of taught differential (minimum 1 °C)

#### Adjustments

TEACH configuration

#### Indicators

One bicolor (Green/Red) status LED, one Amber LED (see Indicators on p.

#### Remote Teach Input

Impedance: 3 kΩ

#### Construction

Threaded Barrel: 304 stainless steel Push Button Housing: ABS/PC Push Button: Santoprene Lightpipes: Acrylic

#### **Operating Conditions**

–20 °C to +70 °C (–4 °F to +158 °F)

#### **Environmental Rating**

Leakproof design, IP67; NEMA 6

#### **Temperature Warm-Up Time**

5 minutes

# Certifications





# **Required Overcurrent Protection**



WARNING: Electrical connections must be made by qualified personnel in accordance with local and national electrical codes and

Overcurrent protection is required to be provided by end product application per the supplied table.

Overcurrent protection may be provided with external fusing or via Current Limiting, Class 2 Power Supply.

Supply wiring leads < 24 AWG shall not be spliced.

For additional product support, go to www.bannerengineering.com.

Supply Wiring (AWG)	Required Overcurrent Protection (Amps)	
20	5.0	
22	3.0	
24	2.0	
26	1.0	
28	0.8	
30	0.5	

## Protection contre la surintensité requise



AVERTISSEMENT: Les raccordements électriques doivent être effectués par du personnel qualifié conformément aux réglementations et codes électriques nationaux et locaux.

Une protection de surintensité doit être fournie par l'installation du produit final, conformément au tableau fourni.

Vous pouvez utiliser un fusible externe ou la limitation de courant pour offrir une protection contre la surtension dans le cas d'une source d'alimentation de classe 2.

Les fils d'alimentation < 24 AWG ne peuvent pas être raccordés.

Pour obtenir un support produit supplémentaire, rendez-vous sur le site www.bannerengineering.com.

Câblage d'alimentation (AWG)	Protection contre la surtension requise (ampères)	
20	5.0	
22	3.0	
24	2.0	
26	1.0	
28	0.8	
30	0.5	

# **Application Note**

The following are examples of materials with high and low emissivity. Additional examples can be found online.

# Sensor-Friendly Materials Materials to Sense with Caution (High Emissivity) (Low Emissivity)

- Aluminum anodized
- Asphalt
- Brick
- Carbon lampblack or plate material
- · Cardboard corrugated or chipboard
- Concrete
- Glass smooth, lead, or borosilicate (e.g., Pyrex®)
- Gypsum (including finished boards)
- Ic
- Iron and steel (except bright galvanized)
- Paper most types, regardless of color
- Styrofoam® insulation
- Plastics
- Water
- · Wood most types

- Aluminum plain or highly polished
- Copper
- Galvanized iron
- · Stainless steel
- Vapor-deposited materials

## **Dimensions**

All measurements are listed in millimeters, unless noted otherwise.

Figure 4. M18T cabled models





Figure 5. M18T QD models



# Accessories

#### Cordsets

Model	Length	Style	Dimensions	Pinout (Female)
MQDEC2-506	2 m (6.56 ft)	Straight	<del> </del> 44 Typ <del></del>	
MQDEC2-515	5 m (16.4 ft)			
MQDEC2-530	9 m (29.5 ft)			
MQDEC2-550	15 m (49.2 ft)		M12 x 1 ── ø 14.5 ──	1 2
MQDEC2-506RA	2 m (6.56 ft)	Right-Angle	32 Typ   1.26"	1 = Brown
MQDEC2-515RA	5 m (16.4 ft)			
MQDEC2-530RA	9 m (29.5 ft)			2 = White 3 = Blue
MQDEC2-550RA	15 m (49.2 ft)		30 Typ. [1.18"]  M12 x 1	4 = Black 5 = Gray

#### **Brackets**

#### SMB18A

- Right-angle mounting bracket with a curved slot for versatile orientation
- 12-ga. stainless steel
- 18 mm sensor mounting hole
- Clearance for M4 (#8) hardware

**Hole center spacing:** A to B = 24.2

**Hole size:**  $A = \emptyset 4.6$ ,  $B = 17.0 \times 4.6$ ,  $C = \emptyset 18.5$ 



#### SMB18SF


- 18 mm swivel bracket with M18
   × 1 internal thread
- · Black thermoplastic polyester
- Stainless steel swivel locking hardware included



Hole center spacing: A = 36.0 Hole size: A = Ø 5.3, B = Ø 18.0

#### SMB18UR

- 2-piece universal swivel bracket
- 300 series stainless steel
- Stainless steel swivel locking hardware included
- Mounting hole for 18 mm sensor



**Hole center spacing:** A = 25.4, B = 46.7 **Hole size:** B =  $6.9 \times 32.0$ , C =  $\emptyset$  18.3

# Additional Accessories

#### Laser Alignment Tool - LAT1812

- · Enables easy sensor alignment at long distances.
- Kit includes one SMB1812 bracket and M12 laser emitter.
- Thread bracket housing onto barrel of mounted sensor; M12 laser emitter inserted into housing provides a precise laser spot for aiming temperature sensor. (Refer to Banner data sheet p/n 122529 for more information.)
- · Remove laser emitter before using sensor.



# Banner Engineering Corp. Limited Warranty

Banner Engineering Corp. warrants its products to be free from defects in material and workmanship for one year following the date of shipment. Banner Engineering Corp. will repair or replace, free of charge, any product of its manufacture which, at the time it is returned to the factory, is found to have been defective during the warranty period. This warranty does not cover damage or liability for misuse, abuse, or the improper application or installation of the Banner product.

THIS LIMITED WARRANTY IS EXCLUSIVE AND IN LIEU OF ALL OTHER WARRANTIES WHETHER EXPRESS OR IMPLIED (INCLUDING, WITHOUT LIMITATION, ANY WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE), AND WHETHER ARISING UNDER COURSE OF PERFORMANCE, COURSE OF DEALING OR TRADE IS AGE

This Warranty is exclusive and limited to repair or, at the discretion of Banner Engineering Corp., replacement. IN NO EVENT SHALL BANNER ENGINEERING CORP. BE LIABLE TO BUYER OR ANY OTHER PERSON OR ENTITY FOR ANY EXTRA COSTS, EXPENSES, LOSSES, LOSS OF PROFITS, OR ANY INCIDENTAL, CONSEQUENTIAL OR SPECIAL DAMAGES RESULTING FROM ANY PRODUCT DEFECT OR FROM THE USE OR INABILITY TO USE THE PRODUCT, WHETHER ARISING IN CONTRACT OR WARRANTY, STATUTE, TORT, STRICT LIABILITY, NEGLIGENCE, OR OTHERWISE.

Banner Engineering Corp. reserves the right to change, modify or improve the design of the product without assuming any obligations or liabilities relating to any product previously manufactured by Banner Engineering Corp. Any misuse, abuse, or improper application or installation of this product or use of the product for personal protection applications when the product is identified as not intended for such purposes will void the product warranty. Any modifications to this product without prior express approval by Banner Engineering Corp will void the product warranties. All specifications published in this document are subject to change; Banner reserves the right to modify product specifications or update documentation at any time. Specifications and product information in English supersede that which is provided in any other language. For the most recent version of any documentation, refer to:

For patent information, see www.bannerengineering.com/patents.



# **X-ON Electronics**

Largest Supplier of Electrical and Electronic Components

Click to view similar products for Industrial Temperature Sensors category:

Click to view products by Banner manufacturer:

Other Similar products are found below:

590-59CN02-103 HEL-705-U-0-12-C1 HEL-736-U-2-36 519-39AW09-245 519-39CH01-295 535-32AB36-202 535-32AB37-202 535