

Solar Guide Light Model GSK-1004

This circuit illuminates 5 LED's when there is not sufficient sunlight for the solar panel to charge batteries. The LED's will automatically turn on and draw voltage from the batteries when the solar panel can no longer convert sunlight to DC voltage.

Technical Specifications

- Power Source: 3 rechargeable double AA batteries (not included)
- Power consumption: 2.5 mA (standby), 80 mA (working)
- Recharging circuit: Built in solar panel
- Solar panel: 4 VDC, 60 mA
- Intensity adjust: potentiometer
- PCB dimensions: 2.39 x 1.70 inches

Operating Principles

This circuit consists of two parts, the charger and sensor. When the solar panel is facing sunlight it will convert the suns energy to DC voltage and run through transistors 1 and 3 charging the rechargeable batteries. The sensors are activated when the photo-transistor (solar panel) does not receive sufficient sunlight the internal resistance becomes greater triggering transistor 5 to light all LED's. Illumination intensity is controlled through transistor 2 and variable resistor 1.

Circuit Assembly


Please refer to Figures 1, 2, and 3 for aid in component placement. It is recommended to start with lower components i.e. diodes, resisters, electrolyte capacitors, and transistors. Be careful to check polarity before soldering. If a problem is detected it is best too use a desoldering pump or desoldering braids to remove component. This will minimize potential damage to the printed circuit board.

Testing

Turn the solar panel to receive the maximum sunlight. The LED's should be off as the circuit is in the recharging cycle. Cover or remove the solar panel from the sunlight and all 5 LED's should light. Set intensity by adjusting variable resistor 1.

Note

This solar panel will not convert fluorescent light to DC voltage.



Special handling instruction


Extra care must be taken to ensure proper installation of solar panel to PCB. Server damage may occur to the solar panel if the positive and negative poles are short circuited when soldering.

Troubleshooting

This circuit has only a few components. The main cause of problems will come from misplaced components or faulty soldering. Utilize figures 2 and 3 to ensure proper placement/ polarity and then check solder points for connectivity.

Accessories

Use GSB-03 (sold separately) to house the PCB and batteries.



X-ON Electronics

Largest Supplier of Electrical and Electronic Components

Click to view similar products for Component Kits category:

Click to view products by Global Specialties manufacturer:

Other Similar products are found below :

 T107/C
 5210211
 KIT-ENERGY HARVEST
 KIT PROTO SHIELDS
 GSK-1004
 G30-7100
 G10-7100
 G30-8000
 BOX3-1455L-BK
 4504

 B03-7100
 B04-7100
 B05-7100
 2450L/C603D
 L201DC
 L/C-201DL
 L/C-805DS
 KBOX1-AC-SV-PR2H
 L/C-603DS
 RGCBNJ660P22
 B10

 8000
 B20-7100
 B45-8000
 MH-1
 MH-2
 TW-E41-1020
 TW-E41-1060
 B04-8000
 B03-8000
 G10-8000
 KBOX3-AL-SV-POW
 B05-8000

 G20-7100
 GSK-820
 GSK-1001
 GSK-944
 GSK-409
 GSK-918
 JRG01-EXP2
 JRG01-EXP1
 G20-8000
 977990
 CCAUTO-LAB1
 CC-LAB2

 JRG01-KIT
 JRG01-PARTS
 JRG01-PCB
 6002-240-001
 GSC-DL020
 GSK-1005