



Sep.1.2021 Copyright 2021 HIROSE ELECTRIC CO., LTD. All Rights Reserved.
 In case of consideration for using Automotive equipment / device which demand high reliability, kindly contact our sales window correspondents.

1	2	3	4						
COUNT	DESCRIPTION OF REVISIONS	BY	CHKD	DATE	COUNT	DESCRIPTION OF REVISIONS	BY	CHKD	DATE
1	DIS-C-000664	T.H.E.K		07.09.06					



NOTE.1 APPLICABLE CRIMP CONTACT:
 RP13A-SC-222(CL113-0151-0)
 THIS CONTACT IS FOR
 APPLICABLE CABLE AWG#24 TO 28 OR EQUIVALENT.

2 APPLICABLE CRIMP CONTACT EXTRACTION TOOL:
 RP13A-SC-TP(CL150-0022-8)

3 THIS PRODUCT IS DELIVERED DISASSEMBLED.

NO.	MATERIAL	FINISH, REMARKS	NO.	MATERIAL	FINISH, REMARKS
4	BRASS		7	FLEXIBLE POLYVINYL CHLORIDE	(BLACK)
3	POLYCARBONATE	(BLACK) UL94V-0	6	BRASS	(BLACK) CHROMATE TREATMENT (TRIVALENT CHROMIUM) JIS B 1111 M2×0.4×4
2	POLYCARBONATE	(BLACK) UL94V-0	5	STEEL	NICKEL PLATING
1	POLYCARBONATE	(BLACK) UL94V-0			

CODE NO. (OLD) CL	DRAWN M. Ishihara	DESIGNED E. Yumino	CHECKED H. Zemba	APPROVED M. Sato	RELEASED
	05.09.30	05.09.30	05.09.30	05.09.30	

SCALE 2 : 1	DRAWING NO. EDC4-023504-71	PART NO. RP13A-12PK-15SC(71)
	UNITS mm	CODE NO. CL113-0219-2-71

TO
R

X-ON Electronics

Largest Supplier of Electrical and Electronic Components

Click to view similar products for [Circular Push Pull Connectors](#) category:

Click to view products by [Hirose](#) manufacturer:

Other Similar products are found below :

[6407-249V-11273P](#) [6408-201V-13273](#) [6408-202V-13343](#) [6408-202V-17343](#) [EZG.0B.309.CLN](#) [FFA.2S.310.ZLA](#) [FGA.1B.307.CYCD72Z](#)
[FGJ.1B.304.CLLD76](#) [FGJ.1B.306.CWLD72](#) [FGJ.3B.304.CYMD10Z](#) [FGJ.3B.304.CYMD82Z](#) [PCS.01.250.DLLE24](#) [PHG.0K.305.CYMC40Z](#)
[PHG.1K.308.CLLK85](#) [PKG.M0.6BL.LZ](#) [PLC.M1.0SL.LA](#) [GMA.10.290.DN](#) [GMA.3B.090.DA](#) [PRG.M0.6GL.LC52GZ](#) [PSA.1S.275.CTLC66](#)
[ABF.1S.250.NTA](#) [133020F](#) [1331ER193MZ](#) [1332M107MZ](#) [DTS26Z19-32JA-LC](#) [DTS26Z19-32SA](#) [DTS26Z19-32SA-LC](#) [DTS26Z23-55HA](#)
[DTS26Z23-55HA-LC](#) [DTS26Z23-55JA-LC](#) [EAJ.1B.306.CWA](#) [ECG.XB.312.CLL](#) [1589430-2](#) [EEA.0B.305.CLN](#) [EEA.0B.309.CLL](#)
[ELF.00.250.NTL](#) [ERA.01.250.DLL](#) [BRD.0B.200.PCSG](#) [BRR.2S.200.PZVG](#) [HR10A-P](#) [CAH.M34.SLL.C72GZ](#) [CAJ.M34.SLL.C72GZ](#)
[300500](#) [ESB.00.303.NLL](#) [EXG.0B.309.HLN](#) [FFB.1S.250.CLAC27](#) [FGA.2B.306.CYCD92](#) [FGA.2B.306.CYCD92Z](#) [FGA.XB.312.CLAD72](#)
[FGJ.1B.302.CYMD62](#)