

This document was generated on 11/04/2019

## PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION

Part Number: 1301790327

Status: Active

Overview: Aero-Motive Repair Parts and Accessories

**Description:** Secondary Support Wire for RF & BF Balancers and Torque Reels

**Documents:** 

RoHS Certificate of Compliance (PDF)

General

Product Family Tool Supports
Series 130179
Cable Length N/A
Duty N/A
Exclude SD Check Yes

Overview <u>Aero-Motive Repair Parts and Accessories</u>

Product Name Aero-Motive

Type Replacement Part, Secondary Support

UPC 78678884921

**Physical** 

Cable Diameter N/A Cable Movement N/A Drum Lock None Mounting Style N/A Packaging Type Carton **Travel Distance** N/A Weight Range N/A Wire/Cable Type N/A

**Material Info** 

Engineering Number SSPBR

Image coming soon

Series image - Reference only

EU ELV

**Not Relevant** 

EU RoHS China RoHS

Not Reviewed REACH SVHC Not Reviewed Halogen-Free Status

**Not Reviewed** 

For more information, please visit Contact US

China ROHS Not Reviewed ELV Not Relevant RoHS Phthalates Not Reviewed

Search Parts in this Series

130179 Series

This document was generated on 11/04/2019

PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION

## **X-ON Electronics**

Largest Supplier of Electrical and Electronic Components

Click to view similar products for Fiber Optic Connectors category:

Click to view products by Molex manufacturer:

Other Similar products are found below:

0004700001 6100-R 6313 F709034706 F709722200 F709730000 F718183204 F727403500 F727752800 FCXO-12-3BY FOSCREW(M2X6) 9440F20-27S-190 944-120-6001 944-125-6003 9441F10SL-3P 953-101-5310-P 954-101-57202B A0270169 12-9122 125702 143025NC DSAKB AX101713 AX102420 AX103923 AX104193 AX104230 AX104562 AX104683 AX105203-B25 AX105205-S1
EHSC2M 17-300800 180-044NF06-11-2S 180-044NF06-17-8P 180-044NF07-11-2S 181-011-126 181-011-S 181-057-126 BT34IW
HRFCP-HSCJ-1(61) HRFC-R2(40) NKSOPBUY 20500002116 2064996-1 20800001065 2170 9132 2612 2620