

VW3A9404

control card fan kit - for variable speed drive - ATV61/ATV71

Product availability: Stock - Normally stocked in distribution facility



Main

Accessory / separate part category	Installation accessories
Accessory / separate part type	Fan kit
Accessory / separate part designation	Control card fan kit
Product compatibility	ATV71HD22M3X ATV71HD18M3X ATV61HD11Y ATV61HU55Y ATV61HD30Y ATV71HU75Y ATV71HU40Y ATV71HU22Y ATV61HD15Y ATV61HU30Y ATV71HD30Y ATV71HD22N4 ATV61HU75Y ATV61HD18Y ATV71HD11Y ATV61HD22N4 ATV71HD15Y ATV71HD22Y ATV61HD22M3X ATV61HD18M3X ATV71HU30Y ATV61HU40Y ATV71HU55Y ATV61HD22Y ATV71HD18Y
Accessory / separate part destination	Variable speed drive
Range compatibility	Altivar 71 Altivar 61
Product specific application	Enables drive to operate at a temperature of 50 to 60 °C Prevents the formation of hot spots

Complementary

Kit composition	1 manual 1 fan subassembly Fixing accessories
-----------------	---

Ordering and shipping details

Category	22135 - ATV61-71 ACCESSORIES
Discount Schedule	CP4C
GTIN	00785901597551
Nbr. of units in pkg.	1
Package weight(Lbs)	1.4000000000000001
Returnability	Y
Country of origin	FR

The information provided in this documentation contains general descriptions and/or technical characteristics of the performance of the products contained herein. This documentation is not intended as a substitute for and is not to be used for determining suitability or reliability of these products for specific user applications. It is the duty of any such user or integrator to perform the appropriate and complete risk analysis, evaluation and testing of the products with respect to the relevant specific application or use thereof. Neither Schneider Electric Industries SAS nor any of its affiliates or subsidiaries shall be responsible or liable for misuse of the information contained herein.

Offer Sustainability

California proposition 65	WARNING: This product can expose you to chemicals including:
----- Substance 1	Lead and lead compounds, which is known to the State of California to cause cancer and birth defects or other reproductive harm.
----- Substance 2	Bisphenol A (BPA), which is known to the State of California to cause birth defects or other reproductive harm.
----- More information	For more information go to www.p65warnings.ca.gov

Contractual warranty

Warranty period	18 months
-----------------	-----------

X-ON Electronics

Largest Supplier of Electrical and Electronic Components

Click to view similar products for [Motor Drives](#) category:

Click to view products by [Schneider](#) manufacturer:

Other Similar products are found below :

[GMA02](#) [R7DBP02L](#) [1300920283](#) [GMA20](#) [R88ACRKN020CRE](#) [R88DUA03LAAC100V30W](#) [R88DUP03LAAC100V30W](#)
[MFECA0050EAM](#) [MFECA0030EAM](#) [1300920078](#) [R88D-GT04H](#) [R88D-KT01H](#) [R7D-BP01H](#) [R88ACR1A005CF](#) [R88D1SN04HECT](#)
[R88D1SN08HECT](#) [R88ACR1A003CFRA](#) [K6CMISZBI52](#) [KLC35BE](#) [R88A-CA1A010B](#) [ST10-IP-EE](#) [ST10-Q-RN](#) [103H7121-0410P](#)
[103H7123-0440P](#) [103H7126-0740P](#) [103H7126-5740P](#) [103H7823-5740P](#) [SMCV6150](#) [U-PKZ0\(480V60HZ\)](#) [ODE-3-120070-1F1A-01](#) [ODE-](#)
[3-240041-3F4B](#) [ODE-3-120070-1F1B-01](#) [132B0107](#) [68581737](#) [3AUA0000072069](#) [3AUA0000089109](#) [ODE-3-220105-1F4B](#)
[1SFA897103R7000](#) [1SFA897102R7000](#) [3AUA0000058190](#) [68581974](#) [68581796](#) [MCD 201-007-T4-CV1](#) [3AUA0000039627](#)
[3AXD50000031889](#) [ATS22D17Q](#) [3AXD50000716630](#) [3AUA0000058169](#) [ATV610U55N4](#) [ATV310H075N4E](#)