

372-3 Ohmmeter

MODEL 372-3 Ohmmeter, 0.2 to 50 M Ω

Provides a wide range of resistance measurements in a small package, .02 ohm to 50 megohms.

Especially useful for checking submersible pumps.

Ideal for use in schools, on test benches or at incoming inspection facilities.

• Ranges: $0\text{-}500\Omega$; $0\text{-}5K\Omega$; $0\text{-}50K\Omega$; $0\text{-}500K\Omega$; 0-5 Meg Ω and 0-50 Meg Ω

• Top Center Scale: 5Ω ; 50Ω ; 500Ω ; $5K\Omega$

• Bottom Center Scale: $30K\Omega$; $300K\Omega$

• Accuracy: ± 3° of Linear Arc Length

• Includes: Batteries and Alligator Clip Leads part # 07500

Range	Center (Ohms)	Maximum Current (Zero Ohms)	Maximum Voltage (Open Circuit)
RX 1	5	340 mA	1.5V
RX 10	50	30 mA	1.5V
RX 100	500	3 mA	1.5V
RX 1000	5 K	0.3 mA	1.5V
RX 10K	30 K	0.65 mA	21.5V
RX 100K	300 K	65 μΑ	21.5V



Battery Required: 1.5 "C", NEDA 14A (Qty: 1) 18V Battery Assembly (Qty: 1)

Ordering Information -			
COMPACT METER	Catalog No.		
372-3 Ohmmeter	12311		
	,		
ACCESSORIES			
Case, Brown Padded Polyester	00836		
Leads	07500		
18V Battery Assembly	00840		

Efficient Customer Service has been a valuable tool for generations of Simpson customers.

Customer Service offers ongoing support for our products and calibration and repair service for all current test equipment.

To obtain service for a discontinued Simpson product, contact Customer Service for assistance.

We offer information regarding our capabilities and referrals to other service centers.

Call (715) 588-3311

X-ON Electronics

Largest Supplier of Electrical and Electronic Components

Click to view similar products for Analogue Multimeters category:

Click to view products by Simpson manufacturer:

Other Similar products are found below:

<u>45026 GVT-417B 12392 PT-350 P3201 P3202 P3203 P3204 P3385 C.A 5001 C.A 5003 P01196522F C.A 5011 AX-7020 P01196521F</u>
12227 12226 12388 12391 12396 40027 12113 12267 HV-44A VP40 PT-300