

Product Change Notification

Date: July 28, 2017

PCN - 9210

Title Change:

22 & 26 SOLDER CONTACTS - DRILL DEPTH CHANGE

Product (s) Affected:

17982-XPG-3ES, 17982-XPG-300, 17982-XSG-3ES, 17982-XSG-300, 17982H-XPG-3ES,
16982-XPG-5XX, 18982-XPG-5XX, 16982-XSG-5XX, 18982-XSG-5XX,

17882-4PG-3ES, 17882-4PG-300, 17882-4SG-3ES, 17882-4SG-300, 16882-4PG-5XX,
18882-4PG-5XX, 16882-4SG-5XX, 18882-4SG-5XX,
W7882-XPG-3ES, W7882-XPG-300, W7882-XSG-3ES, W7882-XSG-300, W6882-XPG-5XX,
W8882-XPG-5XX, W6882-XSG-5XX, W8882-XSG-5XX

Reason for Change:

TO HAVE A CONTACT THAT CAN BE UTILIZED IN OUR PANEL ASSEMBLIES WITH AND WITHOUT EPOXY. CURRENT SOLDER CONTACT FILLS UP WITH EPOXY WHEN EPOXY IS APPLIED TO PANEL BACK WELL.

Description of Change:

ON SIZE 22 SOLDER CONTACT, DRILL DEPTH CHANGED FROM .141 TO .110 AND REMOVED WEEP HOLE. ON SIZE 26 SOLDER CONTACT, DRILL DEPTH CHANGED FROM .180 TO .120 AND REMOVED WEEP HOLE. AFFECTS STRIP LENGTH OF WIRE CONDUCTORS APPLIED TO SOLDER CUPS, CONDUCTOR STRIP LENGTH SHOULD BE APPROXIMATELY .125. ON ASSEMBLY 17982-XSG-3XX THE HEIGHT INCREASED FROM .130 TO .143.

Estimated Schedule for Change:

4TH QUARTER OF 2017; RUNNING CHANGE TO USE UP REMAINING CONTACTS ON CABLE CONNECTORS AND PANEL CONNECTORS WITHOUT EPOXY

Customer Acknowledgement

(To be filled out by customer and returned to Conxall)

The indicated Customer Notification letter was received and acknowledged by the undersigned authority.

Name: _____
Signature _____ Print _____

Company: _____ Location: _____

Title: _____ Date: _____

Please return the signed PCN form to the attention of:

Switchcraft Customer Service Department

jpulliam@switchcraft.com

or Fax: 630-834-8540

X-ON Electronics

Largest Supplier of Electrical and Electronic Components

Click to view similar products for SWITCHCRAFT manufacturer:

Other Similar products are found below :

[TT91002](#) [6006L](#) [60324L](#) [60KD4M](#) [M444B](#) [MMVP48K175T](#) [MMVP96K3NNT](#) [1200](#) [12011](#) [QGPK1CAT5E](#) [12JL6M](#) [D6MBAU](#) [13033T](#)
[13382-10PG-321](#) [RMAS1](#) [DS317](#) [E3FAUQG](#) [E3FDAU](#) [E3FDB](#) [E3FDRAAU](#) [E3FDRAU](#) [E3FDSTAU](#) [E3FDSTBAU](#) [E3FRAAUQG](#)
[E3FSTAUQG](#) [E3FSTB](#) [E3FSTBAU](#) [E3MAU](#) [E3MAUQG](#) [EHW800X2PKG](#) [160](#) [EMHB](#) [MT334B](#) [EN3C11F26](#) [EN3P2MRAPCX](#)
[MVP32K1NTX](#) [18QA18](#) [18QF18](#) [18QK18](#) [20QD20N4](#) [20QF20](#) [20QF20N2](#) [20QF20N6](#) [P10834](#) [P2724](#) [JP9922](#) [K132](#) [240](#) [9144](#) [982A01R](#)