



						DELETED		(11)
	1	1	1	1	003-0861-0001	SEALING SLEEVE	SILICONE RUBBER MIL-R-5847	(10)
4	1	1	1	1	003-0938-0002	MIDDLE SLEEVE	LEADED COPPER	(9)
4	1	1	1	1	003-0939-0002	INNER SLEEVE	BRASS, QP-B-626	(8)
	1	1	1	1	003-0937-0001	CABLE INSULATOR	TEFLON PER L-P-403	(7)
	1	1	1	1	003-1301-0001	BODY INSULATOR	TEFLON PER L-P-403	(6)
4	1	1	1	1	003-0807-0002	PIN CONTACT	COPPER ALLOY	(5)
5	4				003-1295-0004	HOUSING SUB-ASSY NUT-1/4" HEX W/WIRE HOLES		(4)
4		1			003-1295-0003	HOUSING SUB-ASSY NUT-1/4" HEX		(3)
4			1		003-1295-0002	HOUSING SUB-ASSY NUT-1/4" KNURL		(2)
4				1	003-1295-0001	HOUSING SUB-ASSY NUT-1/4" PARTIAL HEX		(1)
	4	3	2	1	COMPONENT	NOMENCLATURE	MAT'L & SPEC.	ITEM
	DASH NO. *				No.			

7. CABLE ACCOMMODATION DIMS:  
 JACKET DIA. ----- .110 MAX  
 DIELECTRIC DIA. ----- .057-.070  
 INNER CONDUCTOR DIA. - .009-.019  
 FOR USE WITH EXTRUDED OR WRAPPED JACKET

6. FOR ELECTRICAL & MECHANICAL SPECS. SEE MALCO CATALOG.

5. .016 DIA. WIRE HOLE 3 PLACES

4. GOLD PLATE PER MIL-G-45204 TYPE II, GRADE C, CLASS I.

3. DELETED

2. SEE RF-ASMB-8 ASSY INSTRUCTIONS. SPECIAL TOOL REQUIRED: CONTACT CRIMP: 010-0134-0000 & LOCATOR 001-0104-0000. ALTERNATE TOOL 010-0065-0000 (NO LOCATOR REQUIRED) HOUSING CRIMP: 010-0082-0000.

1. THIS CONNECTOR MATES WITH ALL 50 Ω GOLDEN CRIMP, CRIMP SILVER & ALL S-50 JACKS & RECEPTACLES AS LISTED IN MALCO CATALOG.

NOTES: UNLESS OTHERWISE SPECIFIED

K	2317	REVISED & REDRAWN 3-3-78	TL	3/15/78	RD
L	24132	NOTE 2 WAS: ... ASSY TOOL REQ'D 010-0065-0000 OR 010-0134-0000 FOR CONTACT, 010-0082-0000 FOR HOUSING. NOTE 3 WAS: ... CENTER CONDUCTOR 5-1-75 2man	TL	5/14/79	RD
M	38493	UPDATE REV. LETTER.	TL	1/22/82	RD
ASSEMBLY	NO REQ'D				
NEXT ASSEMBLIES	LET	ECO	REVISION DESCRIPTION	BY	DATE APP

STANDARD TOLERANCES UNLESS OTHERWISE SPECIFIED  
 DEC. ± \_\_\_\_\_  
 FRAC. ± \_\_\_\_\_  
 ANGLES ± \_\_\_\_\_  
 ECCENTRICITY \_\_\_\_\_  
 MAX. T.I.R. \_\_\_\_\_  
 HOLE DIA. ± \_\_\_\_\_  
 SURFACE ROUGHNESS \_\_\_\_\_ MICRO INCHES  
 THREADS TO MIL-S-7742  
 COMMERCIAL TOLERANCES APPLY TO STOCK DIMENSIONS

**MALCO**  
 A MICRODOT COMPANY, INC.  
 220 PASADENA AVE., SO. PASADENA, CALIF.

SURFACE TREATMENT: NOTED

MATERIAL: NOTED

APP: \_\_\_\_\_  
 CHECKED BY: CH  
 DRAWN BY: D.D.  
 SCALE: \_\_\_\_\_ WT: \_\_\_\_\_ DATE: 3-3-78  
 DRAWING NUMBER: CDM 132-0114-000\* M

**PLUG ASSEMBLY**  
 NON-ENVIRONMENTAL  
 GOLDEN CRIMP 50Ω (RG-188)

## X-ON Electronics

Largest Supplier of Electrical and Electronic Components

*Click to view similar products for [RF Connectors / Coaxial Connectors](#) category:*

*Click to view products by [TE Connectivity](#) manufacturer:*

Other Similar products are found below :

[8915-1511-000](#) [89674-0827](#) [6001-7071-019](#) [6002-7051-003](#) [6002-7551-202](#) [6059674-1](#) [619550-1](#) [630059-000](#) [M39030/3-01N](#) [6500-7071-046](#) [6769](#) [CX050L2AQ](#) [7002-1541-010](#) [7002-1542-011](#) [7004-1512-000](#) [7009-1511-004](#) [7010-1511-000](#) [7029-1511-060](#) [7101-1541-010](#) [7101-1571-002](#) [7105-1521-002](#) [7145-1521-002](#) [7203-1571-003](#) [7209-1511-011](#) [7210-1511-015](#) [7210-1511-019](#) [73137-5015](#) [73216-2241](#) [73404-2300](#) [7405-1521-005](#) [7405-1521-802](#) [8527](#) [8547](#) [FS11V](#) [877931](#) [9049-9513-000](#) [9074-9513-000](#) [9101-9573-002](#) [910A205F](#) [9130-9573-002](#) [PL11SC-026](#) [PL375-33](#) [PL40-5](#) [PL74C-221](#) [PL75MC-217](#) [PL803-7](#) [1200690078](#) [1-201144-1](#) [R107003010W](#) [R110A172100](#)