

TE Connectivity

PCN Date: 02-FEB-16

Product Change Notification Current Date: 17-Feb-2016

Customer: Waldom Electronics Corp (167882)

Product Change Notification: P-16-012580

Location: Rockford

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

AFFECTS CUSTOMER SHIPMENTS WITHIN NORTH AMERICA ONLY Delay of Migration: Southwest DC to New El Paso DC

Description of Changes

UPDATE TO PCN P-16-012528. To ensure a smooth and stable transition from SWDC to EPDC, TE will be delaying the transition from the current Santa Teresa, NM DC (SWDC) to the new El Paso, TX DC (EPDC), originally scheduled to implement February 8th - 15th, is now scheduled to implement April 11th - 15th. This delay will allow extended testing on all SAP systems and procedures to ensure a seamless transition into the new warehouse. As we migrate the product and go-live on the new SAP WM software, it is critical to ensure this testing and training is fully incorporated into the systems and operational processes in the new El Paso warehouse. Based on the revised timing of transition, both Customer Shipments and Supplier Deliveries will continue to process from the Santa Teresa, NM location: Address: 101 Lindbergh, Santa Teresa, NM 88008, DUNS Code: 036967748. See attached Customer Letter.

Customer Letter

Reason for Changes:

Customer Request. The team arrived at this decision to delay the migration with a focus on our customers and to provide a seamless transition to the new warehouse in El Paso. Per PCN P-16-012528, as of the end of August 2015, our current distribution center located in Santa Teresa, New Mexico was divested to Commscope. As a result, TE has established a new Distribution Center in El Paso, TX to support our South-West Customers. In conjunction with the relocation, our new El Paso Distribution Center will be operating on SAP Warehouse Management. The transition will be transparent with the exception of the SAP Packing List. Currently with the use of MOVE in our Santa Teresa DC, Packing Lists can only be printed by carton or by pallet. With the use of SAP Warehouse Management in our El Paso DC, the Packing Lists will be printed by shipment and/or by pallet.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	11-APR-2016
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-178128-2	NO						
1-178128-4	NO						
1-926522-1	NO						
<u>1-962841-3</u>	NO						
<u>1-962918-1</u>	NO						
<u>1-965640-3</u>	NO						
<u>1-965640-6</u>	NO						
<u>1-967616-1</u>	NO						
<u>1-967621-1</u>	NO						
<u>1-967621-3</u>	NO						
<u>1-967621-4</u>	NO						
<u>1-967622-3</u>	NO						
<u>1-967622-5</u>	NO						
<u>1-967622-6</u>	NO						
<u>1-967624-2</u>	NO						
<u>1241372-1</u>	NO						
<u>1241380-2</u>	NO						
<u>1241380-3</u>	NO						
<u>1241381-1</u>	NO						
<u>1241414-1</u>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>1355717-1</u>	NO						
<u>1393431-1</u>	NO			"V23540M7700Y 21"			
<u>140896-2</u>	NO			"815186-000", "AMPS-0- 0140896-2"			
<u>1452653-2</u>	NO						
<u>1452656-2</u>	NO						
<u>1452671-1</u>	NO						
<u>1534594-2</u>	NO						
<u>170031-1</u>	NO			"0-0170031-1"			
<u>170258-2</u>	NO						
<u>170326-1</u>	NO						
<u>170349-2</u>	NO						
<u>172134-1</u>	NO						
<u>172320-2</u>	NO						
<u>172765-1</u>	NO						
<u>172795-1</u>	NO			"0-0172795-1"			
<u>172796-1</u>	NO			"0-0172796-1"			
<u>172864-2</u>	NO						
<u>173724-1</u>	NO			"0-0173724-1"			
<u>1742086-2</u>	NO						
<u>1742087-1</u>	NO						
<u>175019-1</u>	NO			"0-0175019-1"			
<u>175022-1</u>	NO						
<u>175057-1</u>	NO			"0-0175057-1"			
<u>175411-1</u>	NO						
<u>179955-2</u>	NO						
<u>180351-2</u>	NO						
<u>180464-2</u>	NO						
180900	NO			"0-0180900-0", "840946-000",	,		
180907	NO			"AMPS-0-0180900-0" "180907-0", "0-0180907-0"			
	NO			*180907-0*, *0-0180907-0*			
<u>180907-5</u>	NO						
<u>180908</u>	NO			"180908-0", "0-0180908-0", "C89476-000", "AMPS-0- 0180908-0"			
<u>180923</u>	NO			"0-0180923-0"			
<u>180984-5</u>	NO			"0-0180984-5"			
2-160256-2	NO						
<u>2-520102-2</u>	NO			"402646749", "D44822-000", "RAYVOSS-UF-TAB-22- 18TPBR"			
2-520103-2	NO			"D54144-000", "HUB- FULLINSUL-22-18M"			
<u>2-520128-2</u>	NO			"402321202", "E87295-000", "RAYVOSS-UF-FLG-22-			
2-520181-2	NO			18TPBR"			
<u>2-520181-2</u> 2-520183-2	NO			"403041510", "2-42933-5042" "402646756", "A25444-000", "RAYVOSS-UFRCPT-22- 18TPBR", "1146611"			
2-520193-2	NO			"2-42933-5041"			
2-520135-2	NO						
<u>2-520272-2</u>	NO			"D16135-000", "RAYVOSS- UFAST-22-18-TPBR"			
2-520334-2	NO			"038-3990-00"			
2-521102-2	NO						
280755-2	NO						
280756-2	NO						
280756-4	NO						
281742-4	NO						
3-350815-2	NO						
3-350819-2	NO			"402682769", "1062346"			
3-350820-2	NO			"402014575", "A06502-000", "AMPS-3-0350820-2", "110239", "4-16211-4789"			
3-520106-2	NO			"403554751"			
3-520100-2	NO			"403670466"			
3-520110-2	NO			"403670631"			
3-520132-2	NO			105070051			
<u>J-J20140-2</u>	INU	1	<u> </u>	1	ł – – ł		+

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>3-917807-2</u>	NO						
<u>325202</u>	NO			"153568-000", "AMPS-0- 0325202-0"			
<u>336369-1</u>	NO						
<u>4-160971-2</u>	NO						
<u>4-160975-2</u>	NO						
<u>4-520447-2</u>	NO			"405281155"			
<u>4-520448-2</u>	NO			"799338-000", "HUB- FULLINSUL-10-12FM", "1331241"			
<u>41274</u>	NO						
<u>41450-1</u>	NO						
<u>41802</u>	NO						
<u>42037-1</u>	NO						
<u>42068-1</u>	NO						
42100-2	NO						
<u>42117-2</u>	NO						
42238-2	NO						
42281-2	NO			"0-0042281-2"			
42282-2	NO						
42490-3	NO						
42508-2	NO						
42563-8	NO						
42565-2	NO						
42822-2	NO						
42864-2	NO						
5-160446-5	NO						
520963-2	NO						
520974-2	NO						
<u>556136-1</u>	NO						
556137-2	NO						
<u>60249-2</u>	NO						
<u>60295-2</u>	NO			"0-0060295-2"			
<u>61481-1</u>	NO			0-0000233-2			
<u>61588-1</u>	NO						
61944-2	NO			"403546252"			
<u>62050-1</u>	NO			405540252			+
620 <u>50-1</u> 62336-1	NO				+		
63130-2	NO				+		+
<u>63130-2</u> 63138-1	NO						
<u>63196-1</u>	NO						
<u>63498-1</u>	NO			"0-0063498-1"			
<u>7-188275-8</u>	NO						
<u>735411</u>	NO			"148416-000", "AMPS-0- 0735411-0"			
<u>8-188275-0</u>	NO						
<u>925015</u>	NO						
925324-1	NO						
926522-2	NO						
926820-4	NO						
927852-6	NO						
927854-6	NO				1 1		
<u>5270370</u>		1			1		

X-ON Electronics

Largest Supplier of Electrical and Electronic Components

Click to view similar products for Automotive Connectors category:

Click to view products by TE Connectivity manufacturer:

Other Similar products are found below :

003-018-000 600858 60403001 60993906-B 60993913-B 629515004020001 M902-2131 M902-2161 M902-2344 72.330.1035.1 73.353.4028.0 F118010 F119300-B F132210 F132210-B F166900 F180100 F258300 F258300-B F294300-B F339100 F339700 F358300-B F374110 F407400 F412210 F427600 F444110 F487000 F495100-B F500900-B F509500B-B 770444-1 776880-1 827153-1 881735-1 8N1515-32-24P 9-1326727-8 9-1326729-8 925467-1 925474-1 928905-1 936398-2 964562-1 964562-4 964731-2 965051-1 968782-1 GT17SA-8DS-HU GT17VS-10DP-5.2CF