

LOCTITE[®] 330™

November 2007

PRODUCT DESCRIPTION

LOCTITE[®] 330[™] provides the following product characteristics:

Technology	Acrylic		
Chemical Type	Urethane methacrylate ester		
Appearance (uncured)	Slightly cloudy, colorless to pale yellow liquid ^{LMS}		
Components	One component - requires no mixing		
Viscosity	High		
Cure	With activator		
Application	Bonding		

 $\text{LOCTITE}^{\textcircled{8}}$ 330TM is a general purpose adhesive that is used to bond metal, wood, ferrite, ceramic and plastic materials. Applications include tool handles, appliances, sporting goods and decorative trim.

1 0 5

TYPICAL PROPERTIES OF UNCURED MATERIAL

Specific Gravity @ 25 °C Flash Point - See MSDS

Viscosity, Brookfield - RVT, 25 °C, mPa·s (cP):

 Spindle 7, speed 20 rpm
 45,000 to 90,000^{LMS}

 Viscosity, EN 12092 - SV, 25 °C, after 180 s, mPa·s (cP):
 30,000 to 70,000

TYPICAL CURING PERFORMANCE

Cure Speed vs. Substrate

The rate of cure will depend on the substrate used. The graph below shows the shear strength developed with time on grit blasted steel lap shears and tested according to ISO 4587. (Activator 7387[™] applied to one surface).



Cure Speed vs. Bond Gap

The rate of cure will depend on the bondline gap. The following graph shows the shear strength developed with time on grit blasted steel lap shears at different controlled gaps and tested according to ISO 4587. (Activator 7387[™] applied to one surface)



TYPICAL PROPERTIES OF CURED MATERIAL

hysical Properties:	
Coefficient of Thermal Expansion, ISO 11359-2, K ⁻¹	8×10⁻⁵
Coefficient of Thermal Conductivity, ISO 8302, $W/(m \cdot K)$	0.1
Specific Heat, kJ/(kg·K)	0.3

TYPICAL PERFORMANCE OF CURED MATERIAL Adhesive Properties

After 24 hours @ 22 °C, Activator 7387™ on 1 side Lap Shear Strength, ISO 4587:

Mild steel (grit blasted)	 15 to 30 (2,175 to 4,350)
Tensile Strength, ISO 6922:	
Mild steel (grit blasted)	 12 to 22 (1,740 to 3,190)

After 24 hours @ 22 °C, Activator 7387™ or 7386™ on 2 sides Tensile Strength, ISO 6922: Mild steel (grit blasted) N/mm² ≥16.5^{LMS}

lild steel (grit blasted)	N/mm²	≥16.5 ^{⊾MS}	
	(psi)	(≥2,390)	

TYPICAL ENVIRONMENTAL RESISTANCE

Cured for 1 week @ 22 °C, Activator 7387™ on 1 side Lap Shear Strength, ISO 4587: Mild steel (grit blasted): 0.25 mm gap

Hot Strength

Tested at temperature





Heat Aging

Aged at temperature indicated and tested @ 22 °C



Chemical/Solvent Resistance

Aged under conditions indicated and tested @ 22 °C.

		% of initial strength	
Environment	°C	350 h	720 h
Acetone	22	10	10
Motor oil (MIL-L-46152)	87	90	66
Unleaded gasoline	22	20	20
Phosphate ester	87	93	75
Water/glycol 50/50	87	60	60

GENERAL INFORMATION

This product is not recommended for use in pure oxygen and/or oxygen rich systems and should not be selected as a sealant for chlorine or other strong oxidizing materials

For safe handling information on this product, consult the Material Safety Data Sheet (MSDS).

Where aqueous washing systems are used to clean the surfaces before bonding, it is important to check for compatibility of the washing solution with the adhesive. In some cases these aqueous washes can affect the cure and performance of the adhesive.

Directions for use

- 1. For best performance bond surfaces should be clean and free from grease.
- 2. To ensure a fast and reliable cure, Activator 7387[™] or 7386[™] should be applied to one of the bond surfaces and the adhesive to the other surface. Parts should be assembled within 15 minutes.
- The recommended bondline gap is 0.1 mm. Where bond gaps are large (up to a maximum of 0.5 mm), or faster cure speed is required, Activator 7387[™] or 7386[™] should be applied to both surfaces. Parts should be assembled immediately (within 1 minute).
- 4. Excess adhesive can be wiped away with organic solvent.
- 5. Bond should be held clamped until adhesive has fixtured.
- Product should be allowed to develop full strength before subjecting to any service loads (typically 24 to 72 hours after assembly, depending on bond gap, materials and ambient conditions).

Loctite Material Specification^{LMS}

LMS dated March 11, 1996. Test reports for each batch are available for the indicated properties. LMS test reports include selected QC test parameters considered appropriate to specifications for customer use. Additionally, comprehensive controls are in place to assure product quality and consistency. Special customer specification requirements may be coordinated through Henkel Quality.

Storage

Store product in the unopened container in a dry location. Storage information may be indicated on the product container labeling.

Optimal Storage: 8 °C to 21 °C. **Storage below** 8 °C or **greater than 28** °C **can adversely affect product properties** Material removed from containers may be contaminated during use. Do not return product to the original container. Henkel Corporation cannot assume responsibility for product which has been contaminated or stored under conditions other than those previously indicated. If additional information is required, please contact your local Technical Service Center or Customer Service Representative.

Conversions

 $(^{\circ}C \ge 1.8) + 32 = ^{\circ}F$ kV/mm x 25.4 = V/mil mm / 25.4 = inches μ m / 25.4 = mil N x 0.225 = lb N/mm x 5.71 = lb/in N/mm² x 145 = psi MPa x 145 = psi N·m x 8.851 = lb·in N·m x 0.738 = lb·ft N·m x 0.142 = oz·in mPa := cP

Note

The data contained herein are furnished for information only and are believed to be reliable. We cannot assume responsibility for the results obtained by others over whose methods we have no control. It is the user's responsibility to determine suitability for the user's purpose of any production methods mentioned herein and to adopt such precautions as may be advisable for the protection of property and of persons against any hazards that may be involved in the handling and use thereof. In light of the foregoing, Henkel Corporation specifically disclaims all warranties expressed or implied, including warranties of merchantability or fitness for a particular purpose, arising from sale or use of Henkel Corporation's products. Henkel Corporation specifically disclaims any liability for consequential or incidental damages of any kind, including lost profits. The discussion herein of various processes or compositions is not to be interpreted as representation that they are free from domination of patents owned by others or as a license under any Henkel Corporation patents that may cover such processes or compositions. We recommend that each prospective user test his proposed application before repetitive use, using this data as a guide. This product may be covered by one or more United States or foreign patents or patent applications.

Trademark usage

Except as otherwise noted, all trademarks in this document are trademarks of Henkel Corporation in the U.S. and elsewhere. [®] denotes a trademark registered in the U.S. Patent and Trademark Office.

Reference 1.1

X-ON Electronics

Largest Supplier of Electrical and Electronic Components

Click to view similar products for Loctite manufacturer:

Other Similar products are found below :

2003721 2701 5080,GREY 50M X 50MM 37684 GC 10 TYPE 4 (JAR) 97262 406 577, 250ML 603, 10ML 542, 250ML 330, 50ML & 7388, 40ML GLUE REMOVER, 5G 270, 50ML 262, 50ML 40945 98454 3526 SUPER GLUE GLASS, 3G 4080, 50G 460, 50G 641, 50ML 495, 50G 55, 160M 7360 LT 5075 242, 50ML 98472 GC 10 TYPE 3 (JAR) 660, 50ML 3463, 114G 595, 100ML 603, 50ML 2400, 50ML 270 983438 7386, 500ML 572, 50ML 8106, 1L 96001 496, 50G 243, 250ML 5400, 50ML 403, 50G 420, 20G 9464, 50ML 638, 50ML 496, 20G 1487439 3455, 24ML 4062, 20G