


PACKAGE OUTLINE

Three Phase



	Inches	Millimeters
A	3.150	80
B	2.598	66
C	2.008	51
D	0.571	14.5
E	0.157	4
F	0.551	14
G	0.157	4
H	0.571	14.5
I	$\varnothing 0.264$	$\varnothing 6.7$
J	0.630	16
K	----	4-C5
L	0.118	3
M	0.264	6.7
N	0.551	14
O	1.575	40
P	0.276	7
Q	0.394	10
R	0.157	4
S	0.906	23
T	1.063	27
U	1.102	28

Dimensions in inches and (millimeters)