

Wyr-Grid[®] Tools and Hardware

**HNLW12****FR716DR****WGCT-A****WGCT-M**

Part Number	Part Description	Std. Pkg. Qty.	Std. Ctn. Qty.
Hardware			
HNLW12	1/2-13 hex nut and 1/2 lock washer for use in attaching trapeze brackets to threaded rod.	100	—
HNLW12M	12mm hex nut and 12mm lock washer for use in attaching trapeze brackets to threaded rod.	100	—
Tools			
FR716DR	7/16" nut driver for use with the FiberRunner [®] , GridRunner [™] , and Wyr-Grid [®] Systems.	1	10
WGCT-A	Battery powered cutting tool for cutting Wyr-Grid [®] Cable Trays, 2 – 18 volt lithium-ion batteries, and 115 volt, 60 Hz charger included.	1	—
CD-WGCD-1	Wyr-Grid [®] Replacement Cutting Die for the automatic cutting tool.	1	—
WGCT-HEAD	Wyr-Grid [®] Replacement Cutting Head for the automatic cutting tool.	1	—
WGCT-M	Manual cutting tool for cutting Wyr-Grid [®] Cable Trays. Weight: 5.4 lbs. (2.45 kg)	1	—