



C TJS-105

REV.	REVISION	DATE	CHK.	CN#	LET.	REVISION	DATE	CHK.	LET.	DESIGNER	CHECKED BY	DATE	MATERIAL	FINISH	WEIGHT	SCALE 1:1 & NOTED	TITLE	DO NOT SCALE DWG.	SHEET	OF	
0012	F					1) TJS-104-3 WAS TJS-102-5 2) TJS-105-5 WAS TJS-102-1 3) TJS-105-6 WAS TJS-102-2 4) DELETED 2 HOLES & (2) SCREWS, (2) LOCKWASHERS & (2) NUTS	6/7/91														
0021	G	8/21/88				1) TJS-105-9 WAS TJS-105-10 2) TJS-105-6 WAS TJS-105-5 3) TJS-105-7 WAS TJS-105-6	11/8/88														
	E					1) TJS-102-11 WAS TJS-102-9 2) TJS-102-5 WAS TJS-102-4	7/7/91														
	D					1) WAS TJS-106-13	11-8-90														
	C					1) WAS TJS-102-10 LKWSHR 2) MARKING TJS-105 WAS U-94A/U-M9177/5-2 3) CONFIGURATION CHANGED	11/9/90														
	B					1) MARKING TJS-105 WAS U-94A/U-M9177/5-2 2) ADDED ADAPTER & JACK ASSY 3) ADDED 2 SCREWS, 2 LOCKWASHERS & 2 NUTS	5/19/88														
	A						10/8/87														

**NEXUS**  
STAMFORD, CONN.  
DWG. NO. C TJS-105

## X-ON Electronics

Largest Supplier of Electrical and Electronic Components

*Click to view similar products for [Phone Connectors](#) category:*

*Click to view products by [Amphenol](#) manufacturer:*

Other Similar products are found below :

[M444B](#) [6J1041A](#) [R4F](#) [E12BPKG](#) [ECP4PKG](#) [161-3502L-E](#) [MT333X](#) [171-0350-EX](#) [171-101A-EX](#) [171-3325-EX](#) [176S](#) [NC3MG-V](#)  
[NYS228G](#) [P10834](#) [P2380](#) [P2381X](#) [P2411X](#) [P2412](#) [P2724](#) [JM2PB-AU BULK](#) [9144](#) [S2674](#) [280L](#) [163-156N-2-E](#) [163-158N-2-E](#) [171-3308-](#)  
[EX](#) [171-3500-E](#) [2501FT](#) [CMT335](#) [M10662](#) [330Q](#) [RJ5VI-S](#) [40116](#) [TM1R-AU](#) [TM2PBMJ-AU](#) [TM2PJ-AU](#) [TM2PJ-AU BULK](#) [4803.1351](#)  
[49201](#) [49205](#) [TS3PBJ-AU](#) [TS3PBMJ-AU](#) [TT32BX](#) [54B](#) [40112](#) [40205](#) [XMT332B](#) [52170017-331](#) [570](#) [NM3](#)