## DC422 Demo Board Quick Start Guide

Demonstration circuit DC422 is a constant-frequency step-down converter, using the LTC3405 monolithic synchronous buck regulator. The DC422 has an input voltage range of 2.65V to 6V, and is capable of delivering up to 250mA of output current at 1.8V. In Burst Mode<sup>TM</sup>, the DC supply current is typically only 25 $\mu$ A at no load, and less than 1 $\mu$ A in shutdown. For switching-noise-sensitive applications, turn off Burst Mode<sup>TM</sup> by pulling the MODE pin up to V<sub>IN</sub> (jumper JP1 in upper position).

The DC422 demo board features the LTC3405 in a tiny 6-Pin SOT-23 package, operating at 1.5 MHz. This allows the use of low profile surface mount components, ideal for battery-powered, handheld applications.

Gerber files for this circuit are available by calling Linear Technology Corporation at (408) 432-1900.

## **Quick Start Procedure**

Refer to Figure 1 for proper measurement equipment setup and follow the procedure below:

- Note Be careful about which side of the board you use for input, and which you use for output. When the board is right side up (the title is at the top of the board), the output voltage turret is on the *left* side of the board, and the input voltage turret is on the *right* side of the board—opposite of what you might expect.
- 1. Connect the input power supply to the  $V_{IN}$  and GND terminals on the *right side* of the board.
  - **Note** Do not hot-plug  $V_{IN}$  above 5.5V or increase  $V_{IN}$  over the rated maximum supply voltage of 6V. Either condition could damage the part.
- 2. Connect the load between the V<sub>OUT</sub> and GND terminals on the *left side* of the board.
- 3. Select the desired operating mode using JP1.
  - To select pulse-skipping mode, tie the MODE pin to  $V_{IN}$  by inserting the jumper into the lower position. To select Burst Mode<sup>TM</sup> connect the MODE pin to ground by inserting the jumper into the upper position.
  - **Note** Do not leave this pin floating.
- **4.** To shut down the circuit, pull the RUN pin to ground by inserting jumper JP2 into the upper position.




Figure 1. Proper Measurement Equipment Setup

## **X-ON Electronics**

Largest Supplier of Electrical and Electronic Components

Click to view similar products for Power Management IC Development Tools category:

Click to view products by Analog Devices manufacturer:

Other Similar products are found below:

EVAL-ADM1168LQEBZ EVB-EP5348UI MIC23451-AAAYFL EV MIC5281YMME EV DA9063-EVAL ADP122-3.3-EVALZ ADP1300.8-EVALZ ADP130-1.2-EVALZ ADP130-1.5-EVALZ ADP130-1.8-EVALZ ADP1714-3.3-EVALZ ADP1716-2.5-EVALZ ADP1740-1.5EVALZ ADP1752-1.5-EVALZ ADP1828LC-EVALZ ADP1870-0.3-EVALZ ADP1871-0.6-EVALZ ADP1873-0.6-EVALZ ADP1874-0.3EVALZ ADP1882-1.0-EVALZ ADP199CB-EVALZ ADP2102-1.25-EVALZ ADP2102-1.875EVALZ ADP2102-1.8-EVALZ ADP2102-2EVALZ ADP2102-3-EVALZ ADP2102-4-EVALZ ADP2106-1.8-EVALZ ADP2147CB-110EVALZ AS3606-DB BQ24010EVM
BQ24075TEVM BQ24155EVM BQ24157EVM-697 BQ24160EVM-742 BQ24296MEVM-655 BQ25010EVM BQ3055EVM

NCV891330PD50GEVB ISLUSBI2CKIT1Z LM2744EVAL LM2854EVAL LM3658SD-AEV/NOPB LM3658SDEV/NOPB LM3691TL1.8EV/NOPB LM4510SDEV/NOPB LM5033SD-EVAL LP38512TS-1.8EV EVAL-ADM1186-1MBZ EVAL-ADM1186-2MBZ