

HEALTH AND SAFETY AT WORK



HEALTH AND SAFETY AT WORK

Prohibition signs EN ISO 7010:2012

Sign	Symbol	Size	Material	Sign	Symbol	Size	Material
 General prohibition sign	P001	CHH2	F P FM	 No metallic articles or watches	P008	CHH2	F P FM
 No smoking	P002	CHH2	F P FM	 Do not touch	P010	CHH2	F P FM
 No open flame, fire, open ignition source and smoking prohibited	P003	CHH2	F P FM	 Do not extinguish with water	P011	CHH2	F P FM
 No thoroughfare	P004	CHH2	F P FM	 No heavy load	P012	CHH2	F P FM
 Not drinking water	P005	CHH2	F P FM	 No activated mobile phone	P013	CHH2	F P FM
 No access for forklift trucks and other industrial vehicles	P006	CHH2	F P FM	 No access for people with metallic implants	P014	CHH2	F P FM
 No access for people with active implanted cardiac devices	P007	CHH2	F P FM	 No reaching in	P015	CHH2	F P FM

HEALTH AND SAFETY AT WORK

Prohibition signs EN ISO 7010:2012

Sign	Symbol	Size	Material	Sign	Symbol	Size	Material
 Do not spray with water	P016	CHH2	F P FM	 Do not obstruct	P023	CHH2	F P FM
 No pushing	P017	CHH2	F P FM	 Do not walk or stand here	P024	CHH2	F P FM
 No sitting	P018	CHH2	F P FM	 Do not use this incomplete scaffold	P025	CHH2	F P FM
 No stepping on surface	P019	CHH2	F P FM	 Do not use this device in a bathtub, shower or water-filled reservoir	P026	CHH2	F P FM
 Do not use lift in the event of fire	P020	CHH2	F P FM	 Do not use this lift for people	P027	CHH2	F P FM
 No dogs	P021	CHH2	F P FM	 Do not wear gloves	P028	CHH2	F P FM
 No eating or drinking	P022	CHH2	F P FM	 No photography	P029	CHH2	F P FM

HEALTH AND SAFETY AT WORK

Prohibition signs EN ISO 7010:2012

Sign	Symbol	Size	Material	Sign	Symbol	Size	Material
 Do not tie knots in rope	P030	CHH2	F P FM	 Do not wear metal-studded footwear	P035	CHH2	F P FM
 Do not alter the state of the switch	P031	CHH2	F P FM	 No children allowed	P036	CHH2	F P FM
 Do not use for face grinding	P032	CHH2	F P FM	 Do not leave the tow-track	P037	CHH2	F P FM
 Do not use for wet grinding	P033	CHH2	F P FM	 Do not swing the chair	P038	CHH2	F P FM
 Do not use with hand-held grinding machine	P034	CHH2	F P FM	 Hot works prohibited	P039	CHH2	F P FM

If you need any customized sign, please contact our office:
info@anro-safety.com

HOW TO ORDER SIGNS?



HEALTH AND SAFETY AT WORK

Prohibition signs EN ISO 7010:2012

Signs with text					Size	Material					
P001/1		P002/1		P003/1		P004/1		P005/1		C1	F P FM
P006/1		P007/1		P008/1		P010/1		P011/1		C1	F P FM
P012/1		P013/1		P014/1		P016/1		P017/1		C1	F P FM
P018/1		P019/1		P020/1		P021/1		P022/1		C1	F P FM
P023/1		P024/1		P025/1		P026/1		P027/1		C1	F P FM
P028/1		P029/1		P030/1		P031/1		P032/1		C1	F P FM
P033/1		P034/1		P035/1		P036/1		P038/1		C1	F P FM

HEALTH AND SAFETY AT WORK

Mandatory signs EN ISO 7010:2012

Sign	Symbol	Size	Material	Sign	Symbol	Size	Material
 General mandatory action sign	M001	CHH2	F P FM	 Wear safety footwear	M008	CHH2	F P FM
 Refer to instruction manual/booklet	M002	CHH2	F P FM	 Wear protective gloves	M009	CHH2	F P FM
 Wear ear protection	M003	CHH2	F P FM	 Wear protective clothing	M010	CHH2	F P FM
 Wear eye protection	M004	CHH2	F P FM	 Wash your hands	M011	CHH2	F P FM
 Connect an earth terminal to the ground	M005	CHH2	F P FM	 Use handrail	M012	CHH2	F P FM
 Disconnect main plug from electrical outlet	M006	CHH2	F P FM	 Wear a face shield	M013	CHH2	F P FM
 Opaque eye protection must be worn	M007	CHH2	F P FM	 Wear head protection	M014	CHH2	F P FM









HEALTH AND SAFETY AT WORK

Mandatory signs EN ISO 7010:2012

Sign	Symbol	Size	Material	Sign	Symbol	Size	Material
 Wear high-visibility clothing	M015	CHH2	F P FM	 Use barrier cream	M022	CHH2	F P FM
 Wear a mask	M016	CHH2	F P FM	 Use footbridge	M023	CHH2	F P FM
 Wear respiratory protection	M017	CHH2	F P FM	 Use this walkway	M024	CHH2	F P FM
 Wear a safety harness	M018	CHH2	F P FM	 Protect infants eyes with opaque eye protection	M025	CHH2	F P FM
 Wear a welding mask	M019	CHH2	F P FM	 Use protective apron	M026	CHH2	F P FM
 Wear safety belts	M020	CHH2	F P FM	 Check guard	M027	CHH2	F P FM
 Disconnect before carrying out maintenance or repair	M021	CHH2	F P FM	 Keep locked	M028	CHH2	F P FM

HEALTH AND SAFETY AT WORK




















Mandatory signs EN ISO 7010:2012

Sign	Symbol	Size	Material	Sign	Symbol	Size	Material
 Sound horn	M029	CHH2	F P FM	 Close safety bar of chairlift	M033	CHH2	F P FM
 Use litter bin	M030	CHH2	F P FM	 Open safety bar of chairlift	M034	CHH2	F P FM
 Use table saw adjustable guard	M031	CHH2	F P FM	 Immediately leave the tow-track in the event of falling	M035	CHH2	F P FM
 Wear anti-static footwear	M032	CHH2	F P FM	 Lift ski tips	M036	CHH2	F P FM



HEALTH AND SAFETY AT WORK

Mandatory signs EN ISO 7010:2012

Signs with text					Size	Material					
M001/1	 YOUR OWN TEXT	M002/1	 REFER TO INSTRUCTION MANUAL/BOOKLET	M003/1	 WEAR EAR PROTECTION	M004/1	 WEAR EYE PROTECTION	M005/1	 CONNECT AN EARTH TERMINAL TO THE GROUND	C1	F P FM
M006/1	 DISCONNECT MAIN PLUG FROM ELECTRICAL OUTLET	M007/1	 OPAQUE EYE PROTECTION MUST BE WORN	M008/1	 WEAR SAFETY FOOTWEAR	M009/1	 WEAR PROTECTIVE GLOVES	M010/1	 WEAR PROTECTIVE CLOTHING	C1	F P FM
M011/1	 WASH YOUR HANDS	M012/1	 USE HANDRAIL	M013/1	 WEAR A FACE SHIELD	M014/1	 WEAR HEAD PROTECTION	M015/1	 WEAR HIGH-VISIBILITY CLOTHING	C1	F P FM
M016/1	 WEAR A MASK	M017/1	 WEAR RESPIRATORY PROTECTION	M018/1	 WEAR A SAFETY HARNESS	M019/1	 WEAR A WELDING MASK	M020/1	 WEAR SAFETY BELTS	C1	F P FM
M021/1	 DISCONNECT BEFORE CARRYING OUT MAINTENANCE OR REPAIR	M022/1	 USE BARRIER CREAM	M023/1	 USE FOOTBRIDGE	M024/1	 USE THIS WALKWAY	M025/1	 PROTECT INFANTS' EYES WITH OPAQUE EYE PROTECTION	C1	F P FM
M026/1	 USE PROTECTIVE APRON	M027/1	 CHECK GUARD	M028/1	 KEEP LOCKED	M029/1	 SOUND HORN	M030/1	 USE LITTER BIN	C1	F P FM
M031/1	 USE TABLE SAW ADJUSTABLE GUARD	M032/1	 WEAR ANTI-STATIC FOOTWEAR	M033/1	 CLOSE SAFETY BAR OF CHAIRLIFT	M034/1	 OPEN SAFETY BAR OF CHAIRLIFT	M036/1	 LIFT SKI TIPS	C1	F P FM

HEALTH AND SAFETY AT WORK

Warning signs EN ISO 7010:2012

Sign	Symbol	Size	Material	Sign	Symbol	Size	Material
 General warning sign	W001	CHH2	F P FM	 Warning: Drop (fall)	W008	CHH2	F P FM
 Warning: Explosive material	W002	CHH2	F P FM	 Warning: Biological hazard	W009	CHH2	F P FM
 Warning: Radioactive material or ionizing radiation	W003	CHH2	F P FM	 Warning: Low temperature/freezing conditions	W010	CHH2	F P FM
 Warning: Laser beam	W004	CHH2	F P FM	 Warning: Slippery surface	W011	CHH2	F P FM
 Warning: Non-ionizing radiation	W005	CHH2	F P FM	 Warning: Electricity	W012	CHH2	F P FM
 Warning: Magnetic field	W006	CHH2	F P FM	 Warning: Guard dog	W013	CHH2	F P FM
 Warning: Floor-level obstacle	W007	CHH2	F P FM	 Warning: Forklift trucks and other industrial vehicles	W014	CHH2	F P FM








HEALTH AND SAFETY AT WORK

Warning signs EN ISO 7010:2012

Sign	Symbol	Size	Material	Sign	Symbol	Size	Material
 Warning: Overhead load	W015	CHH2	F P FM	 Warning: Sharp element	W022	CHH2	F P FM
 Warning: Toxic material	W016	CHH2	F P FM	 Warning: Corrosive substance	W023	CHH2	F P FM
 Warning: Hot surface	W017	CHH2	F P FM	 Warning: Crushing of hands	W024	CHH2	F P FM
 Warning: Automatic start-up	W018	CHH2	F P FM	 Warning: Counterrotating rollers	W025	CHH2	F P FM
 Warning: Crushing	W019	CHH2	F P FM	 Warning: Battery charging	W026	CHH2	F P FM
 Warning: Overhead obstacle	W020	CHH2	F P FM	 Warning: Optical radiation	W027	CHH2	F P FM
 Warning: Flammable material	W021	CHH2	F P FM	 Warning: Oxidizing substance	W028	CHH2	F P FM

HEALTH AND SAFETY AT WORK

Warning signs EN ISO 7010:2012

Sign	Symbol	Size	Material	Sign	Symbol	Size	Material
	W029	CHH2	F P FM		W033	CHH2	F P FM
Warning: Pressurized cylinder				Warning: Barbed wire			
	W030	CHH2	F P FM		W034	CHH2	F P FM
Warning: Hand crushing between press brake tool				Warning: Bull			
	W031	CHH2	F P FM		W035	CHH2	F P FM
Warning: Hand crushing between press brake and material				Warning: Falling objects			
	W032	CHH2	F P FM		W036	CHH2	F P FM
Warning: Rapid movement of workpiece in press brake				Warning: Sudden loud noise			



HEALTH AND SAFETY AT WORK

Warning signs EN ISO 7010:2012


Signs with text					Size	Material					
W001/1	 YOUR OWN TEXT	W002/1	 WARNING! EXPLOSIVE MATERIAL	W003/1	 WARNING! RADIOACTIVE MATERIAL OR IONIZING RADIATION	W004/1	 WARNING! LASER BEAM	W005/1	 WARNING! NON-IONIZING RADIATION	C1	F P FM
W006/1	 WARNING! MAGNETIC FIELD	W007/1	 WARNING! FLOOR-LEVEL OBSTACLE	W008/1	 WARNING! DROP (FALL)	W009/1	 WARNING! BIOLOGICAL HAZARD	W010/1	 WARNING! LOW TEMPERATURE	C1	F P FM
W011/1	 WARNING! SLIPPERY SURFACE	W012/1	 WARNING! ELECTRICITY	W013/1	 WARNING! GUARD DOG	W014/1	 WARNING! FORKLIFT TRUCKS AND OTHER INDUSTRIAL VEHICLES	W015/1	 WARNING! OVERHEAD LOAD	C1	F P FM
W016/1	 WARNING! TOXIC MATERIAL	W017/1	 WARNING! HOT SURFACE	W018/1	 WARNING! AUTOMATIC START-UP	W019/1	 WARNING! CRUSHING	W020/1	 WARNING! OVERHEAD OBSTACLE	C1	F P FM
W021/1	 WARNING! FLAMMABLE MATERIAL	W022/1	 WARNING! SHARP ELEMENT	W023/1	 WARNING! CORROSIVE SUBSTANCE	W024/1	 WARNING! CRUSHING OF HANDS	W025/1	 WARNING! COUNTERROTATING ROLLERS	C1	F P FM
W026/1	 WARNING! BATTERY CHARGING	W027/1	 WARNING! OPTICAL RADIATION	W028/1	 WARNING! OXIDIZING SUBSTANCE	W029/1	 WARNING! PRESSURIZED CYLINDER	W030/1	 WARNING! HAND CRUSHING BETWEEN PRESS BRAKE TOOL	C1	F P FM
W032/1	 WARNING! RAPID MOVEMENT OF WORKPIECE IN PRESS BRAKE	W033/1	 WARNING! BARBED WIRE	W034/1	 WARNING! BULL	W035/1	 WARNING! FALLING OBJECTS	W036/1	 WARNING! SUDDEN LOUD NOISE	C1	F P FM

HEALTH AND SAFETY AT WORK

Combined signs

Combined signs			Size	Material		
1.0z			7.0z		C1	F P FM
4.0z			8.0z		C1	F P FM

Custom-made signs



CREATE YOUR OWN SIGN












If you are looking for your own sign, please choose the right pictogram and add your own text.

We will print it for you on any material and in any size.

If you have any questions, please contact our office:
info@anro-safety.com

Set of signs

It is also possible to order OHS labels in the form of the following sets. To order a specific set, please select needful pictogram from the Occupational Health and Safety section (p. 36 - 47) or the Chemical Labeling section (p. 60 - 61) . All pictograms on the sheets are available in a format adapted to customer requirements.



HEALTH AND SAFETY AT WORK

Additional health and safety signs

Sign	Symbol	Size	Material	Sign	Symbol	Size	Material
 No entry for unauthorized	V/03	CHH2	F P FM	 Do not cover	V/30	CHH2	F P FM
 Climb forbidden for unauthorized	V/21	CHH2	F P FM	 Do not insert a needle	V/29	CHH2	F P FM
 Occur behind the swivel arm is prohibited	V/33	CHH2	F P FM	 Do not fold	V/31	CHH2	F P FM
 Use conductive shoes	G/33	CHH2	F P FM	 Use face protection	G/09	CHH2	F P FM
 Lift only with help	G/25	CHH2	F P FM	 Use safety harness	G/27	CHH2	F P FM
 Warning: milling wave	W/37	CHH2	F P FM	 Warning: danger of tipping when rolling	W/35	CHH2	F P FM
 Warning: crushing hands	W/19	CHH2	F P FM	 Warning: moving conveyor on track	W/33	CHH2	F P FM

X-ON Electronics

Largest Supplier of Electrical and Electronic Components

Click to view similar products for [Labels and Industrial Warning Signs](#) category:

Click to view products by [ANRO](#) manufacturer:

Other Similar products are found below :

[ESSW30-025](#) [FTP-020P0704](#) [QC101](#) [QC105](#) [QCC613](#) [QCC615](#) [132465](#) [142810](#) [15288](#) [15425](#) [18511](#) [HTS795-1](#) [30288](#) [18432](#) [1878679-3](#)
[2-1878614-6](#) [QC154](#) [QCC612](#) [30545](#) [35070](#) [WM-15-PK](#) [WM-20-PK](#) [06770](#) [11197](#) [111852](#) [111932](#) [KMT-02513V-9](#) [8-1768039-4](#)
[1878983-4](#) [B422](#) [25X85MM](#) [PAXLBK10](#) [LAT-52-361-1](#) [PTL-20-486](#) [PTL-38-486](#) [PTLFT-01-425](#) [13903](#) [11237](#) [18341](#) [18603](#) [29904](#)
[18519](#) [18524](#) [115110](#) [11199](#) [18542](#) [62351](#) [90731](#) [62374](#) [18399](#) [18529](#)