
Replacing the 980/980E Ionized Air Gun Filter

To remove the old filter:


- 1. Turn power off at the AirForce console and disconnect the console from the air supply.
- 2. Hold down the filter release button on the side of the console.
- 3. Remove the hose and filter from the console by pulling the textured rubber plug where the hose emerges from the console. Rocking the plug back and forth can help loosen the filter. Do not pull the hose itself.
- 4. Remove the filter from the hose fitting by depressing the metal release tab on the fitting and pulling the filter off.



To install the new filter:

- Press the metal filter release tab at the end of the air hose until it locks into place.
- 2. Insert the large end of the filter into the opening until it is firmly seated.
- 3. Press the filter release button on the front of the console to lock it down.
- 4. Push the fitting containing the filter all the way into the opening in the console until it latches with a click. It fits only in the correct orientation.

The small plastic fitting on the end of the filter must align with the metal guide coupling in the console. You may have to wiggle the filter slightly while inserting it.



SCS - 926 JR Industrial Drive, Sanford, NC 27332 • (919) 718-0000 • Website: StaticControl.com

X-ON Electronics

Largest Supplier of Electrical and Electronic Components

Click to view similar products for Antistatic Control Products category:

Click to view products by Desco manufacturer:

Other Similar products are found below:

13020 13490 13870 13879 13881 13883 13882 14404 2202SP 3039 37061 42470 09060 09857 42516 37059 04563 17252 19691 19695 09037 09826 09813 66070 100816 68101 68103 98132 73741 13868 13485 13457 13245 13468 13420 13332 13205 13135 91070 8031 8523 66085 40931 37081 13080 13215 13806 73749 010-0225 17260