



PART NUMBER		HOLE DIAMETER	PANEL THICKNESS
NYLON 6/6 RMS-01, NATURAL	FLAME RETARD. NYLON RMS-19, NATURAL		
SMWS-1-01	SMWS-1-19	.070±.002 (1.78±0.05)	.062 (1.57)
SMWS1-1-01	SMWS1-1-19		.093 (2.36)



C	SEE ECN #971 FOR CHANGES	SK 04.01.05
B	SEE ECN #561 FOR CHANGES	SM 01.22.03
A	CHANGED FILE NUMBER	SM 05.29.01
REV	DESCRIPTION	ENGR DATE

TITLE: STANDOFF MICRO WIRE SADDLE			
TOLERANCES UNLESS NOTED	FILE #	DWN: S.M.	APP:
.XX=±.010	MAT'L: SEE TABLE	DT: 11/06/00	DT:
.XXX=±.005	RE: RICHCO, INC.	PO BOX 804238 CHICAGO, IL 60680	
ANG=±1°		(773) 539-4060	
	PART #	DWG IN	PRINT
	SEE TABLE	IN (MM)	TYPE
			CA

## X-ON Electronics

Largest Supplier of Electrical and Electronic Components

*Click to view similar products for [Cable Mounting & Accessories](#) category:*

*Click to view products by [ESSENTRA](#) manufacturer:*

Other Similar products are found below :

[582603-1](#) [009333-000](#) [727844N003](#) [747](#) [809090N001](#) [843188-000](#) [8666](#) [967279N002](#) [DB-11](#) [1300840039](#) [1300900096](#) [1301800416](#)  
[1302264450](#) [1300830184](#) [1300830729](#) [1300900039](#) [1301580036](#) [1301850553](#) [1301860939](#) [1302000074](#) [1302261315](#) [1302264431](#)  
[1337706-2](#) [APA18-AK](#) [1724](#) [1-787307-1](#) [185491N001](#) [1868](#) [HP-6N](#) [C-202-C](#) [202C221-13-0](#) [CA7308-000](#) [8S23-75FR-CS8184](#) [2684](#) [9648](#)  
[3089](#) [988382-000](#) [A72821-000](#) [AA401](#) [173506-000](#) [1823](#) [202C292-13-0](#) [202C302-13-0](#) [2109](#) [300625](#) [3330](#) [3412](#) [356247-1](#) [M9142](#)  
[M9143](#)