

New! Fluke 233 Remote Display Multimeter

Technical Data





The **NEW** Fluke 233 True-rms Remote Display Digital Multimeter allows you to be in two places at once.

- Removable display gives the user ultimate flexibility in unusual measurement scenarios
- Place the display where you can see it and then put the meter where it is convenient for you—no more juggling of leads and the meter while stretching into a tight spot
- Removes the dilemma of trying to take measurements in hard-to-reach places, or making measurements in machines or panels that are physically separated from a limit or isolator switch
- Can be used in areas where the operator can't be close to the active measurement point, like clean rooms or hazardous areas
- True-rms ac voltage and current for accurate measurements on non-linear signals
- Measure up to 1000 V ac and dc
- Measure up to 10 A (20 A for 30 seconds)
- 10,000 µF capacitance range
- Frequency to 50 kHz
- Built in thermometer conveniently allows you to take temperature readings without having to carry a separate instrument
- Resistance, continuity and diode test

Features

• Low power wireless technology allows the display to be carried up to 10 meters (33 ft) away from the point of measurement for added flexibility. No interference with measurements

- The removable magnetic display can be conveniently mounted where it is easily seen
- Make measurements without holding the meter to improve visual focus on probes and augment safe electrical measurements
- Use as a conventional multimeter when the display is connected
- Radio transmitter automatically turns off when the display is connected to the meter
- Auto power off maximizes battery life
- Min/Max and Average recording to capture variations automatically
- Test continuity and diodes
- Easy to read display with large digits and bright backlight
- Battery life approximately 400 hours





Accuracy specifications

lax. resolution	0.1 mV to 1000 V
Accuracy	0.25 % + 2
lax. resolution	0.1 mV to 1000 V
lccuracy	1.0 % + 3
lax. resolution	0.1 mA to 10 A
lccuracy	1.0 % + 3
lax. resolution	0.1 mA to 10 A
lccuracy	1.5 % + 3
lax. resolution	0.1 Ω to 40 MΩ
	6000
	1000 nF to 9999 μF
	0.1 Hz to 50.00 kHz
	-40 °C to +400 °C
	AA batteries: Three for main body; two for display
	400 hours
	2.4 GHz ISM Band 10 meter range
	CAT IV 600 V , CAT III 1000 V
	ccuracy Iax. resolution ccuracy Iax. resolution ccuracy Iax. resolution ccuracy

General specifications

Basic features	
AC true-rms	Yes
Ranging	Auto/Manual
Display	
Backlight	Yes
Data storage	
Min/Max/Avg	Yes
Other features	
Battery type	AA alkaline
Removable display	Yes
Warranty and protection	
Safety rating	CAT IV 600 V/CAT III 1000 V
External protection	Rubber overmold
Warranty	Three-years
Size (H x W x L)	5.3 cm x 5.3 cm x 19.3 cm (2.08 in x 2.08 in x 7.6 in)
Weight	604 g (1.3 lb)



Ordering information:

233 Remote Display Multimeter

Includes: Test leads, alligator clips, 80BK-A temperature probe, manual, CD-ROM, and AA batteries

Optional accessories

TPakMagnetic Hanging Kiti410AC/DC Current Clamp80PK-9General Purpose Probe
(Type K)80AK-4Thermocouple AdapterC35Soft Carry Case



Fluke. Keeping your world up and running.®

Fluke Corporation

PO Box 9090, Everett, WA 98206 U.S.A. Fluke Europe B.V. PO Box 1186, 5602 BD

PO Box 1186, 5602 BD Eindhoven, The Netherlands

For more information call: In the U.S.A. (800) 443-5853 or Fax (425) 446-5116

Fax (425) 446-5116 In Europe/M-East/Africa +31 (0) 40 2675 200 or Fax +31 (0) 40 2675 222 In Canada (800)-36-FLUKE or Fax (905) 890-6866 From other countries +1 (425) 446-5500 or Fax +1 (425) 446-5116 Web access: http://www.fluke.com

©2009 Fluke Corporation. Specifications subject to change without notice. Printed in U.S.A. 8/2009 3476728A D-EN-N

Modification of this document is not permitted without written permission from Fluke Corporation.

X-ON Electronics

Largest Supplier of Electrical and Electronic Components

Click to view similar products for Digital Multimeters category:

Click to view products by Fluke manufacturer:

Other Similar products are found below :

6111-517 FS881 C.A 6133 LAUNCH KIT FLUKE-179-2/IMSK P 1020 A P 1070 P 3315 P 3340 KEWMATE 2000A P 3725 SEFRAM7202 SEFRAM7220 SEFRAM7221 SEFRAM7303 SEFRAM7223 AMP-220-EUR KIT2 BM785 BM789 BS K-CLIP KEW2012RA FLUKE-110/ERTA FLUKE 87-V MAX FLUKE-87V-MAX/E2 KIT P 2005 A P 3349 UT161D DVM821 19290 IBT6K AX-573 C.A 5293-BT 1000-219 1001-613 1006-969 30XR 34XR 35XP TESTO 745 0590 7450 TESTO 760-3 0590 7603 440012 AX-155 AX-174 AX-178 AX-18B AX-190A AX-503 AX-507B AX-594 AX-LCR42A AX-MS811