


Sep.1.2021 Copyright 2021 HIROSE ELECTRIC CO., LTD. All Rights Reserved.  
In case of consideration for using Automotive equipment / device which demand high reliability, kindly contact our sales window correspondents.



NO.	MATERIAL	FINISH . REMARKS	NO.	MATERIAL	FINISH . REMARKS
6	COPPER ALLOY	CONTACT : GOLD PLATED 1.27 μm min LEAD : GOLD PLATED 0.03 μm min UNDER : NICKEL PLATED 1 μm min	13	POLYSTYRENE	
5	COPPER ALLOY	CONTACT : GOLD PLATED 1.27 μm min LEAD : GOLD PLATED 0.03 μm min UNDER : NICKEL PLATED 1 μm min	12	COPPER ALLOY	OVER : TIN PLATED 1 μm min UNDER : COPPER PLATED 0.3 μm min
4	PBT	UL94V-0(BLACK)	11	COPPER ALLOY	OVER : TIN PLATED 1 μm min UNDER : COPPER PLATED 0.3 μm min
3	COPPER ALLOY	CONTACT : GOLD PLATED 1.27 μm min LEAD : GOLD PLATED 0.03 μm min UNDER : NICKEL PLATED 1 μm min	10	POLYCARBONATE	UL94V-2(CLEAR)
2	COPPER ALLOY	CONTACT : GOLD PLATED 1.27 μm min LEAD : GOLD PLATED 0.03 μm min UNDER : NICKEL PLATED 1 μm min	9	POLYCARBONATE	UL94V-2(CLEAR)
1	PBT	UL94V-0(BLACK)	8	PBT	UL94V-0(BLACK)
			7	PBT	UL94V-0(BLACK)

UNITS	SCALE	COUNT	DESCRIPTION OF REVISIONS	DESIGNED	CHECKED	DATE
mm	1 : 1	1	DIS-E-00003936	KIM JAEHYEON	TU. TANIGUCHI	20210305

APPROVED : HO. MIWA	20051017	DRAWING NO.	EDC-122100-50-01
CHECKED : YH. ENAMI	20051014	PART NO.	TM21R-5B-3232D-LP(50)
DESIGNED : TU. TANIGUCHI	20051014	CODE NO.	CL0222-2879-1-50
DRAWN : YK. SATO	20050907		



## X-ON Electronics

Largest Supplier of Electrical and Electronic Components

*Click to view similar products for [Modular Connectors / Ethernet Connectors](#) category:*

*Click to view products by [Hirose](#) manufacturer:*

Other Similar products are found below :

[8949-H88/06BLKA/SN](#) [74441-0010/BKN](#) [MP1010RX-1000](#) [MP44RX-1000](#) [PHJ-4P4C-1-V-4](#) [PHP-6P6C-5](#) [GAX-3-66](#) [GAX-8-62](#) [GDCX-PA-66-50](#) [GDCX-PN-64](#) [GDCX-PN-66](#) [GDCX-PN-66-50](#) [GDLX-A-66](#) [GDLX-N-66](#) [GDLX-S-66](#) [GDLX-S-88K](#) [GDTX-S-88-50](#) [GDX-PA-1010](#) [GLX-N-1010M-BLK](#) [GLX-S-88M-BLK](#) [GMX-N-1010](#) [GMX-S-1010](#) [GMX-S-66](#) [GMX-SMT4-N-88](#) [GPX-2-64](#) [GSGX-N-2-88](#) [GSGX-N-4-88](#) [GSX-NS2-88-3.05](#) [GSX-NS2-88-3.05-50](#) [GSX-NS-88-3.68](#) [PT-108A-8C-UL](#) [PT-J951-8C](#) [PTS-J531-8CS-50UL](#) [1-1775629-2](#) [A-2014-0-4](#) [GWLX-S-88-GR](#) [GWLX-S9-88-YG](#) [DC-1021-8-WH-6](#) [1300530003](#) [1324640-4](#) [RJ11FTVC2G](#) [RJ11FTVC2N](#) [RJFTVX2SA1G](#) [132764-001](#) [1413235](#) [MP88X-1000](#) [MPS88RX-5000](#) [MRJR-5481-0F2](#) [E5288-S000K3-L](#) [E5908-15A242-L](#)