



- 技术要求**
1. 产品无严重损伤、缺针、长短针、旋转针等现象；插针镀层无脱落、起皮、发黄现象。
 2. 未注尺寸公差按SJ1372-78中7级执行。
 3. 每一插针在针座上的固定力 $\geq 10N$ 。
 4. 相同规格产品不同厂家的应能互换。

件(通)用件登记	
插图	
插 图	
插 板	
插 板	
旧底图总号	
底图总号	D 0.9 1.9 3.9 5.9 7.9 9.9 11.9 13.9 15.9 17.9 21.9 23.9 25.9 27.9 29.9
底图总号	C 5.9 7.9 9.9 11.9 13.9 15.9 17.9 19.9 21.9 23.9 25.9 27.9 29.9 31.9 33.9
底图总号	B 4.9 6.9 8.9 10.9 12.9 14.9 16.9 18.9 20.9 22.9 24.9 26.9 28.9 30.9 32.9
底图总号	A 2.0 4.0 6.0 8.0 10.0 12.0 14.0 16.0 18.0 20.0 22.0 24.0 26.0 28.0 30.0
底图总号	孔数 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16

带 针 插 座		PH-2WAP~16WAP		HXY5.566.003	
PH-2WAP~16WAP		(HXY20007-2WAP~16WAP)		材料: 针座: 尼龙U94V-2(0)	
插 针: 黄铜(□0.5*12)		图 样 标 记		材 料	
审 计		审 查		审 定	
工 艺		日 期		日 期	
2011.8.1		2011.8.1		2011.8.1	
共 1 页		第 1 页		8:1	
浙江红星电业有限公司		浙江红星电业有限公司		浙江红星电业有限公司	

X-ON Electronics

Largest Supplier of Electrical and Electronic Components

Click to view similar products for [Headers & Wire Housings](#) category:

Click to view products by [Hongxing](#) manufacturer:

Other Similar products are found below :

[95000-104TRLF](#) [10135584-644402LF](#) [DF62W-EP2022PCA](#) [95000-106TRLF](#) [DF62W-2022SCA](#) [DF62W-EP2022PC](#) [2203348](#) [DF62W-2022SC](#) [1084018](#) [1029039](#) [1084017](#) [802-10-012-10-002000](#) [1112640](#) [1112639](#) [891-007-9SS-BST1T](#) [000-34000](#) [0008550134](#) [0009482033](#) [0009507031](#) [57102-F02-18ULF](#) [57102-S06-03LF](#) [57202-S52-04LF](#) [PCN6-15S-2.5E](#) [0039019024](#) [58102-G61-06LF](#) [582553-1](#) [0009485154](#) [0009508121](#) [0022285053](#) [0050291907](#) [018731A](#) [LY20-4P-DT1-P1E-BR](#) [02.125.8002.8](#) [60101931](#) [60598-1 \(Cut Strip\)](#) [M1625-3R/100](#) [61062-3](#) [61082-181009](#) [CSU011177004](#) [636-1427](#) [638009-1](#) [641938-9](#) [641991-4](#) [644168-1](#) [644827-2](#) [647662-1](#) [65039-019ELF](#) [65692-001LF](#) [65781-018](#) [65781-047](#)