


PCB Layout


2- $\phi$ 0.75 Holes






NO.1	
PART NO	H
A	2.0
B	2.5

NO.4-NO.5	
PART NO	NOTE
01~99	SERIAL NUMBER

NO.2	
PART NO	VIGOR
1	90 $\pm$ 30
3	180 $\pm$ 30
4	250 $\pm$ 30



NO.3	
PART NO	MATERIAL/QTY
S	SUS/1PC
D	SUS/2PCS



⑥	Dust cover	1	KAPTON FILM	Yellow	
⑤	Terminal	2	Phosphor Bronze	Plating silver	
④	Contact	2	F.Ag/SUS		
③	Base	1	Nylon	Black	
②	Cover	1	SUS	Natural	
①	Keystroke	1	Nylon	Black	

APPROVALS		DATE	<p>HONGSHENG ELECTRONICS CO., LTD</p>
DRAWN	xu qi	fengp2014/10/21	

CHECKED		TITLE:	TACT SWITCHS
APPROVALS		PART NO.	K2-1807UD-000W-00
TOLERANCES ARE		SCALE:	1:1
30 $\pm$ 0.15	$\pm$ 0.30	ANGLE	
10 $\sim$ 30	$\pm$ 0.20	UNIT:	mm
5 $\sim$ 10	$\pm$ 0.15	DRAWING NO.	
$\sim$ 5	$\pm$ 0.10		

ECN NO.	REV.	DATE.	DESCRIPTION.	CHANGE.	CHECK.	APPRO.
	A		NEW			

## X-ON Electronics

Largest Supplier of Electrical and Electronic Components

*Click to view similar products for [Tactile Switches](#) category:*

*Click to view products by [HRO parts](#) manufacturer:*

Other Similar products are found below :

[5GTH92001](#) [5GTH9202242](#) [6407-250V-25273P](#) [ADTSA62NV](#) [ADTSA62RV](#) [B3F-3123](#) [1977177-8](#) [1977266-1](#) [ADTSA63NV](#)  
[ADTSM21NSVTR](#) [ADTSM25RVTR](#) [ADTSM32NVTR](#) [ADTSMW64RV](#) [FSMRA4JHA04](#) [GS4.70F300QP](#) [KSC241J SP DELTA LFS](#)  
[3FTL600RAS](#) [3FTL640RAS](#) [Y96K132V0FPLFS](#) [5GTH9658222](#) [ADTSM31NVTR](#) [EVQ-P1D05K](#) [2-1977120-7](#) [TSJW-5.2-260-TR](#)  
[KMT011MNGJLHS](#) [ADTSG648NV](#) [ADTSM62KSVTR](#) [ADTSM648NV](#) [95C06E3RAT](#) [5GTH96561](#) [3ATH9Q](#) [FSM4JSMLXTR](#)  
[FSM4JSMXL](#) [FSMRA8JHA04](#) [HARS0073](#) [Y97HS12A5RAFP](#) [Y97BT23B2HAFP](#) [Y33R411N9FPLFT](#) [Y31C01402FPLFS](#)  
[PTS645SK50SMTR92](#) [ADTSM32NVB](#) [KMS233GPWTLFG](#) [Y78B42324FP](#) [Y33R21116FPLFT](#) [Y31B43131FPLFG](#) [Y78B64124FP](#)  
[Y71243251FP](#) [Y33R31119FPLFT](#) [Y97HS12A5TAFP](#) [PTS638SK25SMTR2LFS](#)