OPTICAL SENSOR LTR-X150P

Description

TEON®

OPTOELECTRONICS

The LTR-X150P is a standalone proximity sensor (PS), with built-in emitter in a single miniature chipled lead-free surface mount package.

Besides, with built-in proximity sensor, this sensor offers the feature to detect object at a user configurable distance.

The sensor has a PS programmable interrupt with hysteresis to response to events and that removes the need to poll the sensor for a reading which improves system efficiency. This CMOS design and factory-set one time trimming capability ensure minimal sensor-tosensor variations for ease of manufacturability to the end customers.

Application

- Control brightness of display panel
- Object detection in mobile, computing, and

consumer devices.

Features

- I²C interface (Standard mode @100kHz or Fast mode @400kHz)
- ultra-small ChipLED package
- Very low power consumption with sleep mode capability
- Operating voltage ranges: 1.7V to 3.6V
- Operating temperature ranges: -40 to +85 °C
- Built-in temperature compensation circuit
- Programmable interrupt function for PS with upper and lower thresholds
- RoHS and Halogen free compliant

PS Features

- Built-in LED driver
- High ambient light suppression
- > 16-bit effective resolution
- Cancellation of crosstalk
 - Programmable LED drive setting

Ordering Information

Part Number	Packaging Type	Package	Quantity
LTR-X150P	Tape and Reel	8-pin chipled package	3,000pcs



OPTICAL SENSOR LTR-X150P

1. Outline Dimensions and Pins Configuration







Pin-Out A	lssignment.
1. VDD	5. LDR
2. SCL	6. NC
3. GND	7. INT
4. LEDA	8. SDA

1. All dimensions in mm 2. Tolerances is +/-0.2 unless specify

Note: All dimension in millimeter

2/33



OPTICAL SENSOR LTR-X150P

2. Functional Block Diagram

The LTR-X150P contains a photodiodes (1 for proximity diode) for photocurrent measurement. The photodiode currents are converted to digital values by ADCs. The sensor also included a LED driver, as well as some peripheral circuits such as an internal oscillator, a current course, voltage reference, and internal fuses to store trimming information.





OPTICAL SENSOR LTR-X150P

3. Application Circuit



Note: It is a requirement to separate the VDD and VLED

In the powering off sequence, the VLED should be powered off first followed by the VDD.

I/O Pins Configuration Table

Pin	I/O Type	Symbol	Description
1		VDD	Supply Voltage
2		SCL	I ² C serial clock
3		GND	GND
4		LEDA	LED Anode.
5	0	LDR	LED driver. To connect to LED Cathode.
6		NC	No Connection on this pin
7	0	INT	Interrupt pin
8	I/O	SDA	I ² C serial data

Recommended Application Circuit Components

Component	Recommended Value
Rp1, Rp2, Rp3 [1]	1 kΩ to 10 kΩ
C1, C3	1uF ±20%, X7R / X5R Ceramic
C2	0.1uF

[1] Selection of pull-up resistors value is dependent on bus capacitance values. For more details, please refer to I²C Specifications: http://www.nxp.com/documents/user_manual/UM10204.pdf

4/33



OPTICAL SENSOR LTR-X150P

4. Ratings and Specifications

Absolute Maximum Ratings at Ta = 25°C

Parameter	Symbol	Min.	Мах	Unit
Supply Voltage	VDD		3.6	V
Digital Voltage Range	SCL, SDA, INT	-0.5	3.6	V
LED Voltage Range	LED	-0.5	4.6	V
LDR Voltage Range	LDR	-0.5	3.6	V
Storage Temperature	T _{stg}	-40	100	°C
Electrostatic Discharge Protection	N		2000	
(Human Body Model JESD22-A114)	Vнвм		2000	V

Note: Exceeding these ratings could cause damage to the sensor. All voltages are with respect to ground. Currents are positive into, negative out of the specified terminal.

Recommended Operating Conditions

Description	Symbol	Min.	Тур.	Max.	Unit
Supply Voltage	VDD	1.7		3.6	V
LED Supply Voltage	V_{LED}	2.8		4	V
Interface signal input high	$V_{l2Chigh}$	1.5		VDD	V
Interface signal input low	V _{I2Clow}	0		0.4	V
Operating Temperature	T _{ope}	-30		85	°C

Electrical & Optical Specifications

All specifications are at VDD = 1.8V, T_{ope} = 25°C, unless otherwise noted.

Parameter	Min.	Тур.	Max.	Unit	Condition
Supply Current		57		uA	MRR 100ms with 8 pulses, 100%duty, 32 us pulse width
Standby Current		1		uA	Shutdown Mode
Wakeup Time from Standby		0.25		ms	From Standby to Active mode where measurement can start



OPTICAL SENSOR LTR-X150P

Characteristics Proximity Sensor

Parameter	Min.	Тур.	Max.	Unit	Condition
PS Resolution			16	Bit	
Sensitivity Range		940		nm	
Detection Distance		20		cm	Pulse Width 32us, 16 pulses, LED Current 104mA
LED Pulse Current			186	mA	Configurable
LED Pulse width			64	us	Configurable for 8,16,32, 64 us
Number of LED Pulses	1		256	Pulses	
Ambient light suppression **			10	klux	Direct sunlight

** Above TBD klux, internal fail-safe feature will force PS count to eight to prevent false trigger.

Typical Device Parameter

(VDD = 1.8V, Ta=25°C, Default power-up settings, unless otherwise noted)







OPTICAL SENSOR LTR-X150P

Electrical Characteristics

All specifications are at VBus = 1.7V, T_{ope} = 25°C, unless otherwise noted.

Parameter	Symbol	Standard mode		Fast mode		
		Min.	Max.	Min.	Max.	Unit
SCL clock frequency	$f_{\rm SCL}$	100		400		kHz
Bus free time between a STOP and START condition	t _{BUF}	4.7	-	1.3	-	us
Hold time (repeated) START condition. After this period, the first clock pulse is generated	t _{HD;STA}	4.0	-	0.6	-	us
LOW period of the SCL clock	t_{LOW}	4.7	-	1.3	-	us
HIGH period of the SCL clock	t _{HIGH}	4.0	-	0.6	-	us
Set-up time for a repeated START condition	$t_{SU;STA}$	4.7	-	0.6	-	us
Set-up time for STOP condition	t _{SU;STO}	4.0	-	0.6	-	us
Rise time of both SDA and SCL signals	t _r	-	1000	-	300	ns
Fall time of both SDA and SCL signals	t_f	-	300	-	300	ns
Data hold time	$t_{HD;DAT}$	0	-	0	-	us
Data setup time	t _{SU;DAT}	250	-	100	-	ns
		/		-		



Definition of timing for I²C bus

7/33



OPTICAL SENSOR LTR-X150P

5. Principles of Operation

I²C Protocols

• I²C Write Protocol (type 1):



· I²C Write Protocol (type 2):



egister

· I²C Read (Combined format) Protocol:



I2C Slave Address

The 7 bits slave address for this sensor is 0x23H. A read/write bit should be appended to the slave address by the master device to properly communicate with the sensor.

I ² C Slave Address									
Command	(0x23H)								(00011)
Туре	Bit7	Bit6	Bit5	Bit4	Bit3	Bit2	Bit1	Bit0	(0X23H)
Write	0	1	0	0	0	1	1	0	0x46H
Read	0	1	0	0	0	1	1	1	0x47H



OPTICAL SENSOR LTR-X150P

6. Register Set

Address	R / W	Register Name	Description	Reset Value
0x81	RW	PS_CONTR	PS operation mode control/SW Reset	0x00
0x82	RW	PS_LED_DUTY_PW	PS LED pulse duty cycle and pulse width setting	0x0E
0x83	RW	PS_LED_CURRENT	PS LED current	0x0F
0x84	RW	PS_N_PULSES	PS number of pulses	0x00
0x93	RW	PS_GAIN	PS Gain setting	0x10
0×04		DO MEAS DATE	PS average	0×40
0,894		F3_MEAS_NATE	PS measurement rate	0249
0x95	RW	PS_LED_DUTY_PW_INV	Invert of 0x82	0x01
0x96	RW	PS_LED_CURRENT_INV	Invert of 0x83	0x10
0x97	RW	PS_N_PULSES_INV	Invert of 0x84	0xFF
0x99	R	PS_STATUS	PS Status	0x00
0x9A	R	PS_DATA_LSB	PS measurement data, LSB	0x00
0x9B	R	PS_DATA_MSB	PS measurement data, MSB	0x00
0xA7	RW	INTERRUPT	Interrupt settings	0x40
0xA8	RW	INTERTUPT_PERSIST	PS interrupt persist setting	0x00
0xA9	RW	PS_THRES_HIGH_LSB	PS interrupt upper threshold, LSB	0xFF
0xAA	RW	PS_THRES_HIGH_MSB	PS interrupt upper threshold, MSB	0xFF
0xAB	RW	PS_THRES_LOW_LSB	PS interrupt lower threshold, LSB	0x00
0xAC	RW	PS_THRES_LOW_MSB	PS interrupt lower threshold, MSB	0x00
0xAD	RW	PS_XTALK_LSB	Xtalk correction on PS, LSB	0x00
0xAE	RW	PS_XTALK_MSB	Xtalk correction on PS, MSB	0x00
0xB3	R	PART_ID	Part Number ID and revision IDs	0x9C
0xB4	R	MANUFAC_ID	Manufacturer ID	0x05
0xB6	RW	PS_CONFIG_1	PS configuration register 1	0xF5
0xDB	RW	PS_CONFIG_2	PS configuration register 2	0x14
0xE3	RW	PS_CONFIG_3	PS configuration register 3	0x67
0xF9	RW	PS_CONFIG_4	PS configuration register 4	0x8F
0xD8	RW	PS_DIODE_SELECT	PS diode select	0x0F



OPTICAL SENSOR LTR-X150P

PS_CONTR Register (0x81) (Read/Write)

The PS_CONTR register controls the PS operation modes and software reset for sensor. The PS sensor can be set to either standby mode or active mode. At either of these modes, the I2C circuitry is always active. The default mode after power up is standby mode. During standby mode, there is no PS measurement performed but I2C communication is allowed to enable read/write to all the registers.

0x81	PS_CONTR (default = 0x00)									
	Bit 7	Bit 6	Bit 5	Bit 4	Bit 3	Bit 2	Bit 1	Bit 0		
	Smart persist Enable	Reserved		PS_16 BITS_EN	PS_OS	FTN/NTF Enable	PS Mode	SW Reset		

Field	Bits	Default	Descri	ption			
			Enable	fast PS threshold persistence check which can be done within 1			
Smart	7	0	measu	rement time setting.			
persist EN	/	0	0	Disable (default)			
			1	Enable			
Reserved	6:5	00	Must w	rrite as 00			
PS_16BITS	4	0	0	Output 11 bits with data cap at 11 bits only (default)			
_EN	4	0	1	Output 16 bits			
			PS offs	et cancellation. When enabled, PS DATA will be subtracted with PS			
	2		OFFSE	OFFSET register data, 0xAD,0xAE			
P5_05	3	0	0	Disabled (default)			
			1	Enabled			
FTN/FTN	0	0	0	Disable FTN/NTF Status reporting (default)			
EN	2	0	1	Enable FTN/NTF Status reporting			
DOMODE	4	0	0	Stand-by mode (default)			
PSMODE	I	0	1	Active mode			
			Reset r	egisters to default values, with sensor into standby mode.			
SW_RST	0	0	0 No action (default)				
			1	Reset Registers to default values (including calibration values)			



Part No. : LTR-X150P

BNS-

OPTICAL SENSOR LTR-X150P

PS_LED_DUTY_PW Register (0x82) (Read/Write)

PS LED duty cycle and pulse width settings. Must be written in tandem with inverted register 0x95.

0x82	PS_LED_D	PS_LED_DUTY_PW (default = 0x0E)							
	Bit 7	Bit 6	Bit 5	Bit 4	Bit 3	Bit 2	Bit 1	Bit 0	
		Rese	erved		PLED Pu	lse Duty	PLED Pu	lse Width	

Field	Bits	Default	Description		
Reserved	7:4	0000	Must write 0000		
			00	25%	
PLED Pulse	2.2	11	01	50%	
Duty	3:2	11	10	75%	
			11	100% (default)	
		10	PS LED (ON-time pulse width.	
			00	8us	
PLED Puise Width	1:0		01	16us	
			10	32us (default)	
			11	64us	

PS_LED_CURRENT Register (0x83) (Read/Write)

PS LED Current settings. Must be written in tandem with inverted register 0x96.

0x83	PS_LED_Current (default = 0x0F)							
	Bit 7	Bit 7 Bit 6 Bit 5 Bit 4 Bit 3 Bit 2 Bit 1 Bit 0						
		Reserved		LED Current				

Field Bits Default Description

12/33



OPTICAL SENSOR LTR-X150P

Reserved	7:5	000	Must write 000				
			LED current se	election			
			00000	0 mA			
			00001	7 mA			
			00010	13 mA			
			00011	20 mA			
			00100	27 mA			
			00101	33 mA			
			00110	40 mA			
			00111	47 mA			
			01000	53 mA			
			01001	60 mA			
			01010	67 mA			
			01011	73 mA			
			01100	80 mA			
LED	4.0	0 01111	01101	87 mA			
Current	4.0	01111	01110	93 mA			
			01111	100 mA (default)			
			10000	107 mA			
			10001	113 mA			
			10010	120 mA			
			10011	127 mA			
			10100	133 mA			
			10101	140 mA			
			10110	147 mA			
			10111	153 mA			
			11000	160 mA			
			11001	167 mA			
			11010	173 mA			
			11011	180 mA			
			111xx	186 mA			



OPTICAL SENSOR LTR-X150P

PS_N_PULSES Register (0x84) (Read/Write)

This register controls number of PS LED pulses. Must be written in tandem with inverted register 0x97.

0x84	PS_N_PUL	PS_N_PULSES (default = 0x00)							
	Bit 7	Bit 6 Bit 5 Bit 4 Bit 3 Bit 2 Bit 1 Bit 0							
				PS Number o	of LED Pulses	;			

Field	Bits	Default	Description	
PS Number of LED Pulses	7:0	0x00	00000000 to 11111111	Specifies PS LED number of pulses. If PS number of pulse set to 0, the pulse count is 1. Maximum is 256 pulses

PS_GAIN Register (0x93) (Read/Write)

0x93	PS_GAIN (PS_GAIN (default = 0x10)							
	Bit 7	Bit 6	Bit 5	Bit 4	Bit 3	Bit 2	Bit 1	Bit 0	
			Rese	erved			PS	Gain	

Field	Bits	Default	Description		
Reserved	7:2	000100	Must write 000100		
		00	00	1x (default)	
DS Coin	1.0		01	2x	
F3 Gain	1.0		10	4x	
			11	8x	

14/33



OPTICAL SENSOR LTR-X150P

PS_MEAS_RATE Register (0x94) (Read/Write)

The PS_MEAS_RATE register controls the timing of the periodic measurements of the PS in active mode. Measurement Repeat Rate is the interval between DATA registers update.

0x94	PS_MEAS_	PS_MEAS_RATE (default = 0xA9)						
	Bit 7	Bit 6	Bit 5	Bit 4	Bit 3	Bit 2	Bit 1	Bit 0
	Reserved	Average Accumulate EN	PS Av Accum	erage/ nulation		PS Measur	ement Time	

Field	Bits	Default	Description		
Reserved	7	1	Must write 1		
Average	C	0	0	Output average data (default)	
Accumulate EN	б	0	1	Output accumulated data	
			Number o	of PS data for averaging	
			00	No average	
PS Average	5:4	10	01	2x average	
Accumulation			10	4x average (default)	
			11	8x average	
			0011	3.125ms	
			0100	6.25ms	
			0101	12.5ms	
PS			0110	25ms	
Measurement	3:0	1001	0111	50ms	
Time			1000	75ms	
			1001	100ms (default)	
			1010	125ms	
			1011	150ms	



OPTICAL SENSOR LTR-X150P

	1100	175ms
	1101	200ms

PS_LED_DUTY_PW_INV Register (0x95) (Read/Write)

Inverted PS_LED_DUTY_PW settings. Must be written in tandem with register 0x82.

0x95	PS_LED_D	PS_LED_DUTY_PW_INV (default = 0x01)								
	Bit 7	Bit 6	Bit 5	Bit 4	Bit 3	Bit 2	Bit 1	Bit 0		
		Rese	erved		PLED PL Inve	ilse Duty erse	PLED Pu Inve	lse Width erse		

Field	Bits	Default	Description		
Reserved	7:4	0000	Must write 0000		
			PS LED p	pulse duty cycle.	
			11	25%	
PLED Puise	3:2	00	10	50%	
Duty Inverse			01	75%	
			00	100%(default)	
			PS LED ON-time pulse width		
			11	8us	
PLED Puise	1:0	01	10	16us	
widen inverse			01	32us (default)	
			00	64us	

PS_LED_CURRENT_INV Register (0x96) (Read/Write)

Inverted PS_LED_Current settings. Must be written in tandem with inverted register 0x83.

0x96	PS_LED_C	URRENT_IN	V (default =	0x10)				
	Bit 7	Bit 6	Bit 5	Bit 4	Bit 3	Bit 2	Bit 1	Bit 0
		Reserved				LED Current		





OPTICAL SENSOR LTR-X150P

Field	Bits	Default	Descript	ion
Reserved	7:5	000	Must wri	te 000
			LED curr	ent selection
			11111	0 mA
			11110	7 mA
			11101	13 mA
			11100	20 mA
			11011	27 mA
			11010	33 mA
			11001	40 mA
			11000	47 mA
			10111	53 mA
			10110	60 mA
			10101	67 mA
LED Current	4.0	10000	10100	73 mA
LED Guilent	4.0	10000	10011	80 mA
			10010	87 mA
			10001	93 mA
			10000	100 mA (default)
			01111	107 mA
			01110	113 mA
			01101	120 mA
			01100	127 mA
			01011	133 mA
			01010	140 mA
			01001	147 mA
			01000	153 mA
			00111	160 mA

17/33



OPTICAL SENSOR LTR-X150P

	00110	167 mA
	00101	173 mA
	00100	180 mA
	000xx	186 mA

PS_ N_PULSES_INV Register (0x97) (Read/Write)

The PS_N_Pulses_INV register activates the PS number of pulse function written in PS_N_Pulses Register (0x84). The value written in PS_LED_INV is inverse value of PS_N_Pulses 0x84.

0x97	PS_N_PUL	PS_N_PULSE_INV (default = 0xFF)								
	Bit 7	Bit 7 Bit 6 Bit 5 Bit 4 Bit 3 Bit 2 Bit 1 Bit 0								
		PS Number of LED Pulses								

Field	Bits	Default	Description		
PS Number of LED Pulses	7:0	0xFF	11111111 to 00000000	Specifies PS LED number of pulses. If PS number of pulse set to 11111111, the pulse count will be 1	

PS_STATUS Register (0x99) (Read Only)

0x99	PS_STATU	PS_STATUS (default = 0x00)								
	Bit 7	Bit 6	Bit 5	Bit 4	Bit 3	Bit 2	Bit 1	Bit 0		
	Rese	erved	FTN	NTF	PS LED Setting Invalid Flag	PS_INT Greater RATE flag	PS_INT status	PS data status		

Field	Bits	Default	Description		
Reserved	7:6	00	-		
FTN	5	0	0	No far to near object detected (default)	

18/33



OPTICAL SENSOR LTR-X150P

			1	Far to near object detected
NTE	4	0	0	No near to far object detected (default)
	4	0	1	Near to far object detected
			PS LED setti	ngs are invalid if the settings in registers 0x95, 0x96
PS LED Setting	2	0	and 0x97 are	not inverse of registers 0x82, 0x83 and 0x84.
Invalid Flag	3	0	0	Valid (default)
			1	Invalid
			This flag to cl	heck PS Integration time greater or less than
PS_INT Greater	2	0	measuremen	t rate
RATE Flag	2	0	0	Less than (default)
			1	Greater than
DC Interrupt Statue	1	0	0	Interrupt signal INACTIVE (default)
PS Interrupt Status	I	0	1	Interrupt signal ACTIVE
BS Data Status	0	0	0	OLD data (data already read) (default)
FS Data Status	0	0	1	NEW data (first time data is read)

PS_DATA Register (0x9A - 0x9B) (Read Only)

PS measurement results are stored in PS_DATA registers. It is necessary to do a block read from registers 0x99 to 0x9C to ensure the data integrity.

Field	Register	Default	Description
PS Data LSB	0x9A	00000000	PS measurement data LSB
PS Data MSB	0x9B	00000000	PS measurement data MSB

AMBIENT_IR_SATURATION Register (0x9C) (Read Only)

0x9C	AMBIENT_	BIENT_IR_SATURATION (default = 0x00)						
	Bit 7	Bit 6	Bit 5	Bit 4	Bit 3	Bit 2	Bit 1	Bit 0
	Reserved	Ambient IR Saturation Flag			Rese	erved		

19/

Part No. : LTR-X150P BNS-



OPTICAL SENSOR LTR-X150P

Field	Bits	Default	Description	
Reserved	7	0	-	
Ambient IR	C	0	0	Ambient IR not saturate (default)
Saturation Flag	ю	0	1	Ambient IR saturate
Reserved	5:0	000000	-	

INTERRUPT Register (0xA7) (Read/Write)

INTERRUPT register controls the operation of the interrupt pin and functions.

0xA7	INT (defaul	t = 0x40)						
	Bit 7	Bit 6	Bit 5	Bit 4	Bit 3	Bit 2	Bit 1	Bit 0
		Rese	erved		Interrupt Polarity	Interrup	ot Mode	Reserved

Field	Bits	Default	Description		
Reserved	7:4	0100	Must write 0100		
Interrunt Delerity	2	0	0	INT pin is active when it is a logic 0 (default)	
Interrupt Polarity	3		1	INT pin is active when it is a logic 1	
		00	00	Interrupt pin is INACTIVE / high impedance state (default)	
	0.1		01	PS measurement can trigger interrupt	
interrupt Mode	2:1				
Reserved	0	0	Must w	rrite 0	



OPTICAL SENSOR LTR-X150P

INTERRUPT_PERSIST Register (0xA8) (Read/Write)

Interrupt persist register sets the N number of times the measurement is out of the threshold range settings before asserting the INTERRUPT pin.

0xA8	INT (defaul	NT (default = 0x00)								
	Bit 7	Bit 6	Bit 5	Bit 4	Bit 3	Bit 2	Bit 1	Bit 0		
		PS_PE	RSIST			Rese	erved			

Field	Bits	Default	Description		
	7:4	0000	0	Every PS value out of threshold range (default)	
			1	1 consecutive PS values out of threshold range	
PS_PERSIST					
			1111	15 consecutive PS values out of threshold range	
Reserved	3:0	0000			

PS_THRESHOLD Register (0xA9 - 0xAC) (Read/Write)

PS_THRESHOLD_HIGH register is used to set the upper limit of the absolute interrupt threshold value. Interrupt functions compare the value in the PS_THRESHOLD_HIGH registers to measured data value in PS_DATA registers. The data format for PS_THRESHOLD_HIGH must be the same as that of PS_DATA registers.

Field	Register	Default	Description
PS_THRES_HIGH LSB	0xA9	11111111	PS upper interrupt threshold value, LSB
PS_THRES_HIGH MSB	0xAA	11111111	PS upper interrupt threshold value, MSB
PS_THRES_LOW LSB	0xAB	00000000	PS lower interrupt threshold value, LSB
PS_THRES_LOW MSB	0xAC	00000000	PS lower interrupt threshold value, MSB



OPTICAL SENSOR LTR-X150P

PS_OFFSET Register (0xAD – 0xAE) (Read/Write)

PS_OFFSET registers let user define PS crosstalk of the device. PS data will be subtracted by this OFFSET value if

PS_OS is enabled at register 0x81.

Field	Register	Default	Description
PS Offset LSB	0xAD	0	PS offset data lower byte
PS Offset MSB	0xAE	0	PS offset data higher byte

PART_ID Register (0xB3) (Read Only)

The PART_ID register defines the part number and revision identification of the sensor.

0xB3	PART_ID (d	PART_ID (default = 0x9C)							
	Bit 7	Bit 7 Bit 6 Bit 5 Bit 4 Bit 3 Bit 2 Bit 1 Bit 0							
		Part Number ID Revision ID							

MANUFAC_ID Register (0xB4) (Read Only)

The MANUFAC_ID register defines the manufacturer identification of the sensor.

0xB4	MANUFAC	MANUFAC_ID (default = 0x05)								
	Bit 7	Bit 7 Bit 6 Bit 5 Bit 4 Bit 3 Bit 2 Bit 1 Bit 0								
		Manufacturer ID								

PS_CONFIG_1 Register (0xB6) (Read/Write)

Field	Bits	Default	Description
Reserved	7:0	11110101	Must write as 11000101

22/33



OPTICAL SENSOR LTR-X150P

PS_CONFIG_2 Register (0xDB) (Read/Write)

Field	Bits	Default	Description
Peserved	7:0 00	00010100	A different value may be recommended depending
Reserved	7.0	00010100	on application

PS_CONFIG_3 Register (0xE3) (Read/Write)

Field	Bits	Default	Description
Reserved	7:0	01100111	A different value may be recommended depending
			on application

PS_CONFIG_4 Register (0xF9) (Read/Write)

Field	Bits	Default	Description
Percented	7:0	10001111	A different value may be recommended depending
Reserved			on application

PS_DIODE_SELECT Register (0xD8) (Read/Write)

0xD8	PS_DIODE_SELECT (default = 0x0F)								
	Bit 7	Bit 6	Bit 5	Bit 4	Bit 3	Bit 2	Bit 1	Bit 0	
	Reserved				СН0_3	CH0_2	CH0_1	СН0_0	

Field	Bits	Default	Description		
Reserved	7:4	0000	Must w	Must write 0000	
DIODE3 switch	3	1	0	OFF	
			1	ON (default)	
DIODE2 switch	2	1	0	OFF	
			1	ON (default)	
DIODE1 switch	1	1	0	OFF	
			1	ON (default)	

23/33



OPTICAL SENSOR LTR-X150P

DIODE0 switch	0	1	0	OFF
			1	ON (default)

7. Application Information

7.1 Operating Mode

Stand-by Mode

The device is by default in stand-by mode after power-up. No measurement activity will be done. I2C protocol allows communication to read/write to the registers. The device can be reset from MCU by setting appropriate register control (SW reset). Start-up sequence is exactly the same as when power-on reset is triggered.

Active Mode

Measurement data is expected to be available within a known fixed time.





7.2 Interrupt Features

The interrupt function is active if PS measurements are outside of the upper and lower absolute threshold levels set in the appropriate threshold register. Only newly measured data is compared to the threshold levels set such

24/33

Part No. : LTR-X150P BNS-



OPTICAL SENSOR LTR-X150P

that old data will not cause triggering of the INT pin if in case the threshold levels are changed in between measurements.

The status of interrupt can be monitored directly through the interrupt (INT) pin or by checking contents of the interrupt register. Interrupt pin can either be enable or disabled. Possible to invert interrupt output of LOW or HIGH state. Interrupt pin IO requirements are exactly the same as those of the I2C bus pins SDA and SCL.

There are two user selectable type of interrupts, which are window interrupt type & logic interrupt type. Refer to Figure 7.3.1 and 7.3.2 for illustration.



Figure 7.3.1 : Interrupt illustration on logic type (with NTF/FTN reporting) (Logic Mode: activated by control register PS_CONTR (0x81<2>) and INTERRUPT (0xA7<1>))







OPTICAL SENSOR LTR-X150P



Figure 7.3.2 : Interrupt illustration on window type (by default, without NTF/FTN reporting)

26/33



OPTICAL SENSOR LTR-X150P

Data Sheet

Flow diagram below illustrates the operation flow, and involving the use of Thresholds and interrupt.





Part No. : LTR-X150P BNS-



OPTICAL SENSOR LTR-X150P

8. Recommended Leadfree Reflow Profile



Process Zone	Symbol	ΔΤ	Maximum ∆T/∆time or Duration
Heat Up	P1, R1	25°C to 150°C	3°C/s
Solder Paste Dry	P2, R2	150°C to 200°C	100s to 180s
Solder Poflow	P3, R3	200°C to 260°C	3°C/s
Solder Reliow	P3, R4	260°C to 200°C	-6°C/s
Cool Down	P4, R5	200°C to 25°C	-6°C/s
Time maintained above liquidus point , 217°C		> 217°C	60s to 90s
Peak Temperature		260°C	-
Time within 5°C of actual Peak Temperature		> 255°C	20s
Time 25°C to Peak Temperature		25°C to 260°C	8mins

It is recommended to perform reflow soldering no more than twice.

28/33



OPTICAL SENSOR LTR-X150P

9. Moisture Proof Packaging

All LTR-X150P are shipped in moisture proof package. Once opened, moisture absorption begins. This part is compliant to JEDEC J-STD-033A Level 3.

10.1 Shelf Life

Device has the shelf life of 12 months if stored in an unopened moisture proof package. It is recommended to store in following condition.

- Shelf Life : 12 months
- Ambient Temperature : <40°C
- Relative Humidity: <90%

10.2 Floor Life

After removal from the moisture barrier bag, the parts should be stored at the recommended storage conditions and soldered within seven days.

- Floor Life : 168 hours
- Ambient Temperature : <30°C
- Relative Humidity: <60%

10.3 Rebaking information

When the moisture barrier bag is opened and the parts are exposed to the recommended storage conditions for more than seven days, the parts must be baked before reflow to prevent damage to the parts.

Baking Conditions

Package	Temperature	Time
In Reels	60°C	48 hours
In Bulk	100°C	4 hours

Baking should only be done once.

29/33

Part No. : LTR-X150P BNS-



OPTICAL SENSOR LTR-X150P

10. Recommended Land Pattern and Metal Stencil Aperture



Recommended Land Pattern



Note: All dimensions are in millimeters

30/33

Part No. : LTR-X150P BNS-



OPTICAL SENSOR LTR-X150P

Recommended Metal Stencil Aperture

It is recommended that the metal stencil used for solder paste printing has a thickness (t) of 0.11mm (0.004 inches / 4 mils) or 0.127mm (0.005 inches / 5 mils).

The stencil aperture opening is recommended to be 0.40mm x 0.60mm which has the same dimension as the land pattern. This is to ensure adequate printed solder paste volume and yet no shorting.







OPTICAL SENSOR LTR-X150P

11. Package Dimension for Tape and Reel



Notes:

- 1. All dimensions are in millimeters
- 2. Empty component pockets sealed with top cover tape
- 3. 13 inch reel 10,000 pieces per reel
- 4. In accordance with ANSI/EIA 481-1-A-1994 specification

32/33

Part No. : LTR-X150P BNS-



OPTICAL SENSOR LTR-X150P

Revision Table:

Version	Update	Page	Date
1.0	Final datasheet as created	Total 49	4-Mar-2021
1.1	Update Pin 1 chamfer orientation	2	12-May-2021



X-ON Electronics

Largest Supplier of Electrical and Electronic Components

Click to view similar products for Proximity Sensors category:

Click to view products by Lite-On manufacturer:

Other Similar products are found below :

 70.340.1028.0
 70.360.2428.0
 8027AL20NL2CPXX
 9221350022
 922AA2W-A9P-L
 GL-12F-C2.5X10(LOT3)
 972AB3XM-A3P-L
 PS3251

 980659-1
 E2E2-X5M41-M4
 E2E-X14MD1-G
 E2E-X2D1-G
 E2E-X4MD1-G
 E2E-X5E1-5M-N
 E2E-X5Y2-N
 EH-302
 EI3010TBOP

 MS605AU
 EP175-32000
 IC08ANC15PO-K
 IFRM04P1513/S35L
 IFRM06P1703/S35L
 IFRM08P1501/S35L
 IFRM12N17G3/L

 IFRM12P3502/L
 IFRM12P37G1/S14L
 ILFK12E9189/I02
 ILFK12E9193/I02
 OISN-013
 25.352.0653.0
 25.352.0753.0

 25.523.3253.0
 9151710023
 922AA1HI-A4P-L
 922AA2XM-B9P-L
 922FS0.8-H4P-G-020
 922FS1.5C-A4P-Z774
 SC606ABV0S30

 SM552A100
 SM851A1200FP
 F3S-A162-U
 GL-12F-C2X10(LOT10)
 GL-8HIBX10
 QT-08L
 RDS-DIN3-PA-D1
 34.110.0010.0
 3U02
 TL

 C2MF1-M3-E4
 TLX5C1GE
 TLX5C1GE
 SM60
 SM60
 SM60
 SM60
 SM60