

PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION

Part Number: [2054030001](#)
Status: **Active**
Overview: [USB Products and Solutions](#)
Description: USB 2.0 Hub Kit, 100mA, 4 Upstream Ports, 1 Downstream Port, 7 USB 2.0-to-Pico-Lock Cable Assemblies Included

Documents:

[Drawing \(PDF\)](#)

[Datasheet \(PDF\)](#)

[RoHS Certificate of Compliance \(PDF\)](#)

Kit components

Kit Components

(1) PCB Hub Assembly
(2) USB Female-to-Pico-Lock 150.00mm Cable Assembly [2061070001](#)
(2) USB Female-to-Pico-Lock 300.00mm Cable Assembly [2061070002](#)
(2) USB Female-to-Pico-Lock 1.0m Cable Assembly [2061070003](#)
(1) USB Male-to-Pico-Lock 1.0m Cable Assembly [2061070004](#)

General

Product Family

Series

Component Type

Overview

Product Name

UPC

Accessories

[205403](#)

USB Hub Kit

[USB Products and Solutions](#)

USB 2.0 Hub Solutions

191128890663

Physical

Circuits (Loaded)

Color - Resin

Net Weight

Number of Rows

Packaging Type

N/A

Green

215.240/g

1

Carton

Electrical

Current - Maximum per Contact


100mA

Material Info

Reference - Drawing Numbers

Sales Drawing

2012410552-000



Series image - Reference only

EU ELV

Not Relevant

EU RoHS

Compliant with Exemption 7(c)-I*

REACH SVHC

Not Reviewed

Halogen-Free

Status

Not Reviewed

For more information, please visit [Contact US](#)

CUST_NOTE

*Product contains part(s) with customer managed

CUST_NOTE1

EHS data. These part(s) are excluded from product compliance status evaluation.

CUST_NOTE2

China ROHS

50 Image

ELV

Not Relevant

RoHS Phthalates

Not Contained*

Search Parts in this Series

[205403 Series](#)

X-ON Electronics

Largest Supplier of Electrical and Electronic Components

Click to view similar products for [Interface Modules](#) category:

Click to view products by [Molex](#) manufacturer:

Other Similar products are found below :

[IFD8520](#) [cPCI-3544](#) [422CON](#) [ATX6022/14GP7](#) [ATX6022/8](#) [AX93221-24/48](#) [FC6A-EXM2](#) [OPT8AP-AE](#) [60006-016](#) [96RMKVM-19V1C-A](#) [60016-011](#) [60016-014](#) [60006-008](#) [60016-015](#) [60011-075](#) [HPCI-14S12U](#) [cBP-3208](#) [cBP-3062A](#) [FAB205-6P5](#) [ATX6022/6](#) [60016-012](#) [96RMKVM-17V1C-A](#) [PCE-DP10-00A1E](#) [MOS-1120Y-0201E](#) [96RMLCD-17V1-A](#) [96RMKVM-17V8C-A](#) [60004-005](#) [60016-017](#) [60006-019](#) [60006-009](#) [60016-035](#) [60016-034](#) [60016-031](#) [60016-030](#) [60016-026](#) [60016-025](#) [60016-024](#) [60016-021](#) [60016-018](#) [60016-007](#) [60016-006](#) [60016-005](#) [60016-004](#) [60007-002](#) [60006-018](#) [60006-010](#) [AXX10GBTWLHW3](#) [382-BBEH](#) [555-BDCL](#) [GW DEVICE SERVER](#)
[2E/4DB9](#)