

PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION

Part Number: [0733860224](#)
Status: **Active**
Overview: [RF/Microwave Adapters](#)
Description: 50 Ohms, SMB Plug-to-SMA Jack Adapter, One Piece Per Bag

Documents:

| | |
|-------------------------------|--|
| 3D Model | 3D Model (PDF) |
| Drawing (PDF) | RoHS Certificate of Compliance (PDF) |

General

| | |
|-----------------|---------------------------------------|
| Product Family | RF/Coax Connectors |
| Series | 73386 |
| Overview | RF/Microwave Adapters |
| Product Name | Adapter, SMA, SMB |
| Style | Adapter, Between-Series Adapter |
| Type | Subminiature |
| UPC | 884982708464 |
| Wire/Cable Type | N/A |

Physical

| | |
|-----------------------|-----------|
| Gender | Jack/Plug |
| Keying to Mating Part | None |
| Net Weight | 3.021/g |
| Orientation | Straight |
| PCB Mounting | N/A |
| Packaging Type | Bag |
| Panel Mount | No |
| Panel Mount Method | N/A |
| Reverse Polar | No |


Electrical

| | |
|-----------------|-------------------|
| Frequency | 4 GHz |
| Impedance | 50Ω |
| Power / Voltage | See Specification |

Material Info

Reference - Drawing Numbers

| | |
|---------------|------------------|
| Sales Drawing | SD-73386-022-000 |
|---------------|------------------|



Series image - Reference only

EU ELV

Not Relevant

EU RoHS

Compliant with Exemption 6(c)

REACH SVHC

Contained Per -
D(2020)9139-DC (19
Jan 2021)

Lead

Halogen-Free

Status

Low-Halogen

For more information, please visit [Contact US](#)

China ROHS

ELV

RoHS Phthalates

China RoHS

50 Image

Not Relevant

Not Contained

Search Parts in this Series

[73386 Series](#)

X-ON Electronics

Largest Supplier of Electrical and Electronic Components

Click to view similar products for [RF Adapters - Between Series](#) category:

Click to view products by [Molex](#) manufacturer:

Other Similar products are found below :

[5945-9503-000](#) [MCX/F-SMA/M](#) [R192417010](#) [ADBJ20-E1-BJ379](#) [ADM2](#) [ADPL75-A1-PL75](#) [242191](#) [9317505](#) [29-3835P](#) [AD130](#) [ADBJ20-E1-PL74](#) [ADBJ77-A1PL3155](#) [ADBJ77-E1-UPL20](#) [ADRMF370](#) [242190](#) [242215](#) [242228](#) [R125680000W](#) [R192430000](#) [UAD95](#) [1057367-1](#) [8311505](#) [R114704000](#) [R451034500](#) [R451030500](#) [R451543000](#) [HDVDPN](#) [ADBJ20-K1-PL20](#) [R451570000](#) [R192419000](#) [R451034000](#) [J9](#) [J3WE-5](#) [R451032500](#) [242201RP](#) [17K132-K00S5](#) [03K719-S22S3](#) [AD-RSMAF-RTNC](#) [53K156-K00N5](#) [53K160-KIMN1](#) [02K119-K00E3](#) [29S132-K01N5](#) [53S156-K00N5](#) [02S119-S00E3](#) [28K132-K00N5](#) [02S109-K00S3](#) [27-8200TP](#) [242235](#) [ADBJ20-E1-BJ89](#) [ADP-SMAF-MMCXM](#)