


REV	A	CHANGED FILE NO. AND TITLE BLOCK	SM 02.04.02	ENGR DATE
		DESCRIPTION		
		RE:	TOLERANCES UNLESS NOTED .XX=±.010 .XXX=±.005 FRAC=1/64 ANG=1°	
		FILE #	SP2	
		MAT'L:	SEE NOTES	
		DWN:	P.B.	
		APP:		
		DT:	03-11-01	
		DT:	03-11-01	
		RICHCO INC.	RICHCO INC.	
		PO BOX 804238, CHICAGO, 60680	(773) 539-4060	
		SEET TABLE	PART #	
		PRINT TYPE	CA	

TITLE:	SUPPORT POST, TYPE 2
DWG IN	FINAL
IN (MM)	

NOTES:
 1. MATERIAL: NYLON 6/6 (RMS-01).
 FLAME RETARDANT: NYLON (RMS-19),
 AVAILABLE BY SPECIAL ORDER ONLY.
 2. COLOR: NATURAL.



TO SNAP-LOCK IN A .187 ±.003
 (.475 ±0.08) DIA. HOLE, IN A
 .062 (1.57) NOM. THK. BOARD/CHASSIS
 (BOTH ENDS)

PART NO.	SP2-3-01	3/16 (4.8)
	SP2-4-01	1/4 (6.4)
	SP2-6-01	3/8 (9.5)
	SP2-8-01	1/2 (12.7)
	SP2-10-01	5/8 (15.9)
	SP2-12-01	3/4 (19.1)
	SP2-14-01	7/8 (22.2)
	SP2-16-01	1 (25.4)
"A"		±.015 (±0.4)

X-ON Electronics

Largest Supplier of Electrical and Electronic Components

Click to view similar products for [Standoffs & Spacers](#) category:

Click to view products by [Richco](#) manufacturer:

Other Similar products are found below :

[M0513-3-N](#) [M0516-3-N](#) [M0517-3-N](#) [M0518-3-N](#) [M0521-3-N](#) [M0524-3-N](#) [M0532-35-AL](#) [M0532-35-N](#) [M0543-4-AL](#) [M0544-35-N](#) [M0544-3-N](#) [M0545-3-AL](#) [M0553-3-N](#) [M0564-4-N](#) [M0608-5-SS](#) [M0609-5-SS](#) [M0610-35-AL](#) [M0613-3-N](#) [M0651-5-SS](#) [M0653-35-N](#) [M0654-4-SS](#) [M0655-5-AL](#) [M0655-5-N](#) [M0660-4-AL](#) [M0660-4-N](#) [M0670-35-N](#) [M0671-5-N](#) [M0671-5-SS](#) [M0722-5-N](#) [M0725-6-N](#) [M0731-4-N](#) [M0904-B-25-AL](#) [M1273-2545-AL](#) [M1273-3005-AL](#) [M1303-3506-AL](#) [M1307-3506-AL](#) [M1313-3005-N](#) [M1313-4007-AL](#) [M1314-3005-AL](#) [M1314-3005-SS](#) [M1315-3005-SS](#) [M1315-4007-N](#) [M1317-3506-AL](#) [M1317-4007-SS](#) [M1318-3005-SS](#) [M1320-3005-AL](#) [M1320-3005-N](#) [M1321-3005-SS](#) [M1321-4007-AL](#) [M1322-4007-N](#)