

Product availability: Non-Stock - Not normally stocked in distribution facility



### Main

|                           |                         |
|---------------------------|-------------------------|
| Range of product          | TeSys B                 |
| Range                     | TeSys                   |
| Product or component type | Auxiliary contact block |
| Product compatibility     | LC1B<br>CR1B            |
| Pole contact composition  | 1 NC                    |


### Complementary

|                         |  |
|-------------------------|--|
| Mechanical durability   | 1000000 cycles   |
| Connections - terminals | Control circuit : screw connection 1 cable 4 mm <sup>2</sup> - with cable end<br>Control circuit : screw connection 1 cable 6 mm <sup>2</sup> - without cable end<br>Control circuit : screw connection 2 cable 4 mm <sup>2</sup> - with cable end<br>Control circuit : screw connection 2 cable 6 mm <sup>2</sup> - without cable end |

### Ordering and shipping details

|                       |                                    |
|-----------------------|------------------------------------|
| Category              | 22449 - LIMIT SWITCHES,ACCESSORIES |
| Discount Schedule     | T                                  |
| GTIN                  | 00785901643265                     |
| Nbr. of units in pkg. | 1                                  |
| Package weight(Lbs)   | 0.8000000000000004                 |
| Returnability         | N                                  |
| Country of origin     | FR                                 |

### Offer Sustainability

|  |   |
|--|---|
| RoHS (date code: YYWW)                         | Compliant - since 0801 - Schneider Electric declaration of conformity  <a href="#">Schneider Electric declaration of conformity</a>      |
| REACH  | Reference not containing SVHC above the threshold   |
| California proposition 65<br>----- Substance 2 | WARNING: Cancer and Reproductive Harm - <a href="http://www.P65Warnings.ca.gov">www.P65Warnings.ca.gov</a><br>Bisphenol A (BPA), which is known to the State of California to cause birth defects or other reproductive harm. |

### Contractual warranty

|                 |           |
|-----------------|-----------|
| Warranty period | 18 months |
|-----------------|-----------|

The information provided in this documentation contains general descriptions and/or technical characteristics of the performance of the products contained herein. This documentation is not intended as a substitute for and is not to be used for determining suitability or reliability of these products for specific user applications. It is the duty of any such user or integrator to perform the appropriate and complete risk analysis, evaluation and testing of the products with respect to the relevant specific application or use thereof. Neither Schneider Electric Industries SAS nor any of its affiliates or subsidiaries shall be responsible or liable for misuse of the information contained herein.

## X-ON Electronics

Largest Supplier of Electrical and Electronic Components

*Click to view similar products for [Limit Switches](#) category:*

*Click to view products by [Schneider](#) manufacturer:*

Other Similar products are found below :

[5ML1-E1](#) [5ML31](#) [LZG1](#) [LZL1-6C](#) [622EN114-R](#) [622EN18-6](#) [622EN224-6B](#) [622EN230](#) [622EN237-R](#) [622EN69-3](#) [622EN85-RB](#) [MA-10019](#)  
[6PA109](#) [7LS51](#) [83547001](#) [83725002](#) [83830001](#) [83840701](#) [83841001](#) [83881140](#) [8AS42](#) [8LS10](#) [8LS125-4PG](#) [8LS152-4PGN20](#) [914CE16-](#)  
[3A](#) [914CE3-3L1](#) [915PA10](#) [91MCE16-P2O](#) [924CE16-Y3](#) [924CE1-S6](#) [924CE1-T25A](#) [924CE1-T3](#) [924CE1-T9A](#) [924CE2-T9](#) [924CE31-Y20-](#)  
[X5](#) [924CE31-Y3L1](#) [GL-10054](#) [GLDB03C-6](#) [GLDC05C](#) [GLZ324](#) [H3141CAKAA](#) [RDI-G-L5B](#) [DD-10000](#) [DT-2R3-A7](#) [14CE16-3N28](#)  
[14CE18-N15](#) [151ML3-E1](#) [E3102BAAAA](#) [BFL1-AW1-S](#) [1EN329-R](#)