





LET.	C.O.	DATE	OWN.	CHKD.	APP.
D	9244	12-23-74	FM		



1-19-5	STORM GRAY 2-113-7	-7
1-19-5	GREEN 2-113-6	-6
1-19-5	YELLOW 2-113-5	-5
1-19-5	BLUE 2-113-4	-4
1-19-5	RED 2-113-3	-3
1-19-5	BLACK 2-113-2	-2
1-19-5	WHITE 2-113-1	-1
ITEM 2	ITEM 1	P/N

UNLESS OTHERWISE SPECIFIED		 <b>DUNCAN electronics, Inc.</b> <small>A DIVISION OF SYSTRON-DONNER CORPORATION  COSTA MESA, CALIFORNIA</small>	DWG. NAME	
TOLERANCE FRACT. $\pm 1/64$ ANGLE $\pm 1/2^\circ$ XX $\pm .01$ DRILLED HOLE + .003 XXX $\pm .005$ -- .001			<u>KNOB ASS'Y</u>	
CONCENTRICITY .005 T.I.R REMOVE ALL BURRS & SHARP EDGES SURFACE ROUGHNESS MIL-STD-10A ✓		FINISH	MATERIAL	DWG. NO
USED ON	SCALE	COLOR: SEE TABUL.		2-104-
				REV
				D

## X-ON Electronics

Largest Supplier of Electrical and Electronic Components

*Click to view similar products for [Encoders](#) category:*

*Click to view products by [Sensata](#) manufacturer:*

Other Similar products are found below :

[6-1393048-0](#) [6-1393048-5](#) [62AG22-H5-P](#) [62B22-LP-030C](#) [63K25](#) [63K32](#) [63KS100](#) [63KS64](#) [63R100](#) [63R50-020](#) [63RS256-060](#) [700-09-36](#)  
[RE12D300-201-1](#) [1393047-3](#) [2-1393047-2](#) [T101-5C2-111-M1](#) [T101-5C3-111-M1](#) [T101-5C4-111-M1](#) [385001M0439](#) [385001M0216](#)  
[V23401H1409B101](#) [V23401T8002B802](#) [V23401U6019B609](#) [E69-1](#) [E69DF10](#) [E69-FCA](#) [62B11-LP-100S](#) [62B11-LPP-040C](#) [62N11-P](#)  
[62S22-H9-120S](#) [62S30-L0-200C](#) [62V15-02-080S](#) [63K64](#) [63KS100-040](#) [63R64-050](#) [63RS64](#) [700-16-16](#) [V23401D3002B301](#)  
[V23401D1001B102](#) [3-1393048-1](#) [63KS128](#) [63KS256](#) [1-1879391-5](#) [GH65C11-N-SO](#) [62S15-M0-P](#) [1393047-1](#) [E69-FCA02](#) [E69-FCA04](#)  
[E69-DF20](#) [E69-DF2](#)