

TE P/N	TE CD	Nanonics P/N	Part Description
1589052-1	1589052	SSL00511500SCN	Dualobe, 1 row, LCP, 5 position, special 11500 solder cup, receptacle, thread for 1.0 jackscrews.
1589052-2	1589052	SSL00911500SCN	Dualobe, 1 row, LCP, 9 position, special 11500 solder cup, Receptacle, thread for 1.0 jackscrews.
1589052-3	1589052	SSL01511500SCN	Dualobe, 1 row, LCP, 15 position, special 11500 solder cup, receptacle, thread for 1.0 jackscrews.
1589052-4	1589052	SSM00511500SCN	Dualobe, 1 row, metal, 5 position, special 11500 solder cup, receptacle, thread for 1.0 jackscrews.
1589052-5	1589052	SSM01511500SC	Dualobe, 1 row, metal, 15 position, special 11500 solder cup, receptacle.
1589052-6	1589052	SSG00511500SCN	Dualobe, 1 row, gold , 5 position, special 11500 solder cup, receptacle, thread for 1.0 jackscrews.
1589052-7	1589052	SSM02511500SCQ	Dualobe, 1 row, metal, 25 position, special 11500 solder cup, receptacle, thread for 1.2 jackscrews.
1589052-8	1589052	SSM05111500SCN	Dualobe, 1 row, metal, 51 position, special 11500 solder cup, receptacle, thread for 1.0 jackscrews.
1589052-9	1589052	SSS00511500SCN	Dualobe, 1 row, stainless, 5 position, special 11500 solder cup, receptacle, thread for 1.0 jackscrews.
1-1589052-0	1589052	SSM01511500SCN	Dualobe, 1 row, metal, 15 position, special 11500 solder cup, receptacle, thread for 1.0 jackscrews.
1-1589052-1	1589052	SSM00911500SCN	Dualobe, 1 row, metal, 9 position, special 11500 solder cup, receptacle, thread for 1.0 jackscrews.
1-1589052-2	1589052	SSM01511500SCQ	Dualobe, 1 row, metal, 15 position, special 11500 solder cup, receptacle, thread for 1.2 jackscrews.

X-ON Electronics

Largest Supplier of Electrical and Electronic Components

Click to view similar products for [Rectangular Mil Spec Connectors](#) category:

Click to view products by [TE Connectivity](#) manufacturer:

Other Similar products are found below :

[891-011-15SA2-BSST](#) [CTS-S16/16](#) [65002-062](#) [CY4602-000](#) [732-8020-01](#) [77058-22-55PN](#) [81542-20](#) [86.030.0053.0](#) [1241346-1](#) [RM252-020-311-2900](#) [DMC-M 08-16 SA](#) [1589051-4](#) [MSO34MPK1E1](#) [BACC65CAMA](#) [BACC65CP1PN](#) [BACI10BC0816PNBA](#) [HSB-D4S03DM222X](#) [2217548-1](#) [891-006-9PS-BST1T](#) [891-009-15SA2-BRT1T](#) [27963-20T12](#) [SIM2N40NC3](#) [SIM2S100A](#) [1604996-2](#) [SMD25PN90L-4055](#) [1900ND08S1B00A](#) [22628-10-6P-791](#) [RE04-212S](#) [M32139/03-G05SN](#) [CTD160E01F-6148](#) [CTJ112E03B](#) [CTJ122E02D-8000](#) [CTJ-3D-12](#) [CTJ920E06N-513](#) [CTJ920E12N-513](#) [CTL-16-090](#) [RM300-000-581-0000](#) [CY4600-000](#) [CY4601-000](#) [38111-14-15SN](#) [38112-14-15PN](#) [MMA23-0111R1](#) [MMD25-0071P1](#) [33516062020](#) [33526M11-08PE](#) [DMC-M99-01AN](#) [Y59113WE20PNV00300](#) [ZPF000000000106310](#) [105979-31](#) [EN4165M01AD0G0](#)